	ENGINE DETAILS
1. Manufacturer ——	Pratt & Whitney Canada Corp.
2. Type/Model/Series	E.T.C. E- 6 PT6A- 34 B/S: 1218
3. Serial Number	PCE-RB1291

//	new	overhaul					nd
2 3 MAR 2022	0.0	NIA	0	New enging inhibiting and is in c	e final acce run comple ondition fo	ptance test a eted satisfactor r safe operati	oril ion
nstalled this Pratt & 6/N: 100-0313 round runs and leal uality Control:	Whitney Engin I.A.W. Kodia k checks were c	e Model No.: Pak Aircraft Draw good. Aircraft T	T6A-34 S/N: PCF ving #100-171-00 T.:	E-RB1291 00 and serviced Engine T.T.:	on Kodiak Mo with Eastman raft Company, Inc	del No.100 Aircra Turbo Oil 2380. A	aft All
KOD			Make/Model: Aircraft S/N: Aircraft Reg: Eng S/N: Work Order:	Kodiak 100 100-0313 N321KD PCE-RB1291 RS1474	ACTT: Hobbs: Eng TTSN: Eng TSO: Eng Cycles:	145.9 145.9 145.9 N/A 83	
AD COMPLIANCE • FAA Biweekly SCHEDULED	AD resea	arch completed thro	ough FAA Biweekly 2	023-12. See separate	e compliance recor	d for details.	
 Performed 600 hor Performed inspect 	ur fuel pump outlet ion and operational ion of engine control	filter replacement of the filter replacement	d AGB chip detectors ects noted.	5-3A IAW PWC MM IAW PWC MM 79-2	0-02. No defects fil		
 Performed inspecti Performed inspecti Performed inspecti Performed compresion Performed deceleration 	ion of ignition excite ion of ignition cable ssor performance r ation check IAW P	er/current regulator es for chafing, wear recovery compress WC MM 71-00-00 (box for installation a and installation IAW or wash IAW AMM 7 11)(F). No defects no	and condition IAW PV PWC MM 74-20-00. 230.5.2.	VC MM 74-10-00. I	No defects noted.	
 Performed inspecti Performed inspecti Performed compre Performed deceler Performed engine 	ion of ignition excite ion of ignition cable ssor performance r ation check IAW P	er/current regulator es for chafing, wear recovery compress WC MM 71-00-00 (box for installation a and installation IAW or wash IAW AMM 7 11)(F). No defects no	and condition IAW PV PWC MM 74-20-00. 230.5.2.	VC MM 74-10-00. I	No defects noted.	
Performed inspecti Performed inspecti Performed inspecti Performed compre Performed decelera Performed because Performed engine a UNSCHEDULED Engine hot start ext. 72-00-00. No defect facilitate inspection Adjusted air plenum Adjusted low idle No	ion of ignition excit- ion of ignition cable ssor performance in ation check IAW Pi run-up checks IAW ceedance recorded cts noted. Remove IAW PWC MM 73- n shroud latches IA g IAW AMM 7100.	er/current regulator is for chafing, wear recovery compress WC MM 71-00-00 (1 AMM Section 5-7. 1 on 05/15/23 in Ar 1 d and reinstalled F 1-10-05. Leak check W standard practic 5.6.	box for installation at and installation IAW or wash IAW AMM 7 11)(F). No defects no ea B of Figure 502. F RH igniter IAW PWC satisfactory.	and condition IAW PV PWC MM 74-20-00. 230.5.2. oted. Performed hot section	VC MM 74-10-00. I No defects noted.	No defects noted.	
Performed inspecti Performed inspecti Performed inspecti Performed compre Performed deceler: Performed engine in the start extended to the start extended	ion of ignition excit- ion of ignition cable ssor performance in ation check IAW Pi run-up checks IAW ceedance recorded cts noted. Remove IAW PWC MM 73- n shroud latches IA g IAW AMM 7100.	er/current regulator is for chafing, wear recovery compress WC MM 71-00-00 (1 AMM Section 5-7. 1 on 05/15/23 in Ar 1 d and reinstalled F 1-10-05. Leak check W standard practic 5.6.	box for installation at and installation IAW or wash IAW AMM 7 11)(F). No defects no ea B of Figure 502. F RH igniter IAW PWC satisfactory.	and condition IAW PV PWC MM 74-20-00. 230.5.2. oted. Performed hot section	VC MM 74-10-00. I No defects noted.	No defects noted.	
Performed inspection Performed inspection Performed inspection Performed compre Performed decelerate Performed engine in the second se	ion of ignition excition of ignition cable ssor performance ration check IAW Pirun-up checks IAW run-up checks IAW ecedance recordects noted. Remove IAW PWC MM 73-n shroud latches IA g IAW AMM 7100.3 g speed pickup IAW all work was perforal 3021242 Rev67	er/current regulator is for chafing, wear recovery compress WC MM 71-00-00 (if AMM Section 5-7. If on 05/15/23 in And If and reinstalled Fi-10-05. Leak check W standard practic 5.6. W AMM 7600.5.3. In the compression of th	box for installation at and installation IAW or wash IAW AMM 7 11)(F). No defects not be as B of Figure 502. Fix Highiter IAW PWC statisfactory.	nd condition IAW PV PWC MM 74-20-00. 230.5.2. oted. Performed hot section MM 74-20-00. Rem	NO MM 74-10-00. In No defects noted. In borescope insperoved and reinstalled and reinstalled AM902.0 Rev31,	ction IAW PWC MM ed #5 fuel nozzle to	
Performed inspecti Performed inspecti Performed inspecti Performed compre Performed decelera Performed decelera Performed engine a UNSCHEDULED Engine hot start exa 72-00-00. No defect facilitate inspection Adjusted air plenum Adjusted low idle Nadjusted reverse National Results Adjusted reverse National Results PWC Maintenance Manucertify this ENGINE has the aircraft and/or composition.	ion of ignition excition of ignition cable ssor performance ration check IAW Pirun-up checks IAW run-up checks IAW ecedance recordects noted. Remove IAW PWC MM 73-n shroud latches IA g IAW AMM 7100.3 g speed pickup IAW all work was perforal 3021242 Rev67 s been inspected	er/current regulator is for chafing, wear recovery compress WC MM 71-00-00 (if AMM Section 5-7. If on 05/15/23 in And If and reinstalled Fi-10-05. Leak check W standard practic 5.6. W AMM 7600.5.3. In a coordance In accordance with	box for installation at and installation IAW or wash IAW AMM 7 11)(F). No defects not be as B of Figure 502. For installation IAW PWC statisfactory.	Adintenance Manual	NO MM 74-10-00. If No defects noted. In borescope insperoved and reinstalled and reinstalled AM902.0 Rev31,	ction IAW PWC MM ed #5 fuel nozzle to dated 03/22/21 and rworthy condition.	
Performed inspecti Performed inspecti Performed inspecti Performed compre Performed decelera Performed because Performed engine a UNSCHEDULED Engine hot start ext 72-00-00. No defect facilitate inspection Adjusted air plenum Adjusted low idle No	ion of ignition excition of ignition cable ssor performance ration check IAW Pirun-up checks IAW run-up checks IAW ecedance recordects noted. Remove IAW PWC MM 73-n shroud latches IA g IAW AMM 7100.3 g speed pickup IAW all work was perforal 3021242 Rev67 s been inspected	er/current regulator is for chafing, wear recovery compress WC MM 71-00-00 (if AMM Section 5-7. If on 05/15/23 in And If and reinstalled Fi-10-05. Leak check W standard practic 5.6. W AMM 7600.5.3. In a coordance In accordance with	box for installation at and installation IAW or wash IAW AMM 7 11)(F). No defects not be as B of Figure 502. For installation IAW PWC statisfactory.	Adintenance Manual	NO MM 74-10-00. If No defects noted. In borescope insperoved and reinstalled and reinstalled AM902.0 Rev31,	ction IAW PWC MM ed #5 fuel nozzle to dated 03/22/21 and rworthy condition. Regulations and is ed above.	

THE WARRY OF

THE PARTY OF THE P

A STATE OF THE PARTY OF THE PAR	Signature	AME ACA/AMO SCA/AMO
TRIM SPEED Ng,% Ng MAX:	P. WEIGH	
	R. WEISTRA	T.C. 4-58 NO . 123

Engine Airworthiness Directives



Pratt & Whitney Canada Corp. 1000, Marie-Victorin Longueuil, Quebec Canada J4G 1A1

Engine S/N	PCE-RB1291

Reference	A.D.'s	Sign	Lic. #	Data
FAA A.D. 75-06-01	To ensure the early detection of reduction gearbox deterioration and for improved blade containment S.B. 1138, 1216, & 1220 or their later revision or superseding S.B. incorporated at manufacture	R. WEISTRA	or Stamp T.C. 4-58 NO . 123	2 3 MAR 2022
FAA A.D. 75-11-04	For engines incorporating an unmodified power turbine shaft housing assembly part number 3010548. Not applicable due to part number. Modification incorporated at manufacture.	R. WEISTRA	T.C. 4-58 NO . 123	2 3 MAR 2022
CF-78-03	Engine incorporates the improved power turbine containment modification S.B. 1217 & 1220 or their later revision or superseding S.B. Incorporated at manufacture.	R. WEISTRA	T.C. 4-58 NO . 123	2 3 MAR 2022
FAA A.D. 80-08-12	To preclude wear of the fuel pump drive coupling splines.S.B. 1316, 3139 or 12025 or their later revision or superseding S.B. incorporated at manufacture. Inspection requirements of this A.D.	R. WEISTRA	TC. 4-58 NO . 123	2 3 MAR 2022
FAA A.D. 90-12-05	Not Applicable. The engine serial number is not listed in the Applicability section of the A.D.	R. WEISTRA	(C) T.C. 4-58 NO . 123	2 3 MAR 2022
FAA A.D. 92-15-11	To prevent excessive engine acceleration time that could result in an aircraft's inability to safely perform the balked landing maneuver, modification incorporated at manufacture.	R. WEISTRA	T.C. 4-58 NO . 123	2 3 MAR 2022
FAA A.D. 97-04-12	To preclude malfunction of the compressor bleed off valve SB 1538R2, 3344, 4204, 12134, 13287 & 14251 or their later revision or superseding SB incorporated at manufacture.	R. WEISTRA	T.C. 4-58 NO . 123	2 3 MAR 2022
FAA A.D. 2002-23-13	Not Applicable. Compliance to this A.D. is only required for engines that have been overhauled or where the turbine exhaust duct has been subjected to a shop visit where it has been modified, altered or repaired.	R. WEISTRA	T.C. 4-58 NO . 123	2 3 MAR 2022
FAA A.D. 2011-20-51	Not Applicable. The manufacturer , part number and serial number of the First Stage Reduction Sun Gear installed during engine manufacture not listed in the Applicability section of the A.D.	R. WEISTRA	T.C. 4-58 NO . 123	2 3 MAR 2022
FAA A.D 2011-25-12	Not Applicable. The manufacturer, part number and serial number of the First Stage Reduction Sun Gear and associated Planetary Gear Set installed during engine manufacture not listed in the Applicability section of the A.D.	R. WEISTRA	TC. 4-58 NO . 123	2 3 MAR 2022