(Vestern Aircraft Propeller Service 1610 NW Perimeter Way Troutdale, OR 97060 Repair Station FQ6R544N F WO#24131 Sensenich Propeller 74DM6-0-58 B Hub Serial - A51085 Overhaul and Recondition in accordance with Sensenich SPRM590 current revision. H DATE Repairman B component identified above was inspected or repaired in accordance with Current FAA Regulations and found airworthy for return to service. Pertinent Details are on file at this agency under work order number. FAA Repair Station FQ6R544N TSO- 0000 TT- 27.8

COLGAN AIR SERVICES

LACROSSE, WI 54603

DATE: 03-16-2018 A/C tach time: 1128.00 N9746W Piper PA28-140 S/N 28-23229
Installed an overhauled propeller P/N 74DM6-0-58 S/N A51085 from Western Aircraft Propeller, see form 8130-3 dated 2-4-2018. Used new 3/8 propeller mounting bolts (propeller and bolts supplied by the owner) I/A/W Piper PA28-140 maintenance manual. Torqued and saftied the propeller bolts, Reinstalled the spinner. Propeller has TTSO 0 hrs, TTSN 27.8 hrs.

Michael Lubinsky

Annual Inspection / Propeller 05-26-2018 / 1136.0 Tach / Sensenich 74DM6-O-58 SN:A51085 / TT – 35.8 / SOH – 8.0

Inspection Complete per FAR 43 Appendix D- No Service Work Performed

Checked ADs through 2018-11 - None Due

Date Total Prop

MAINT

I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED IAW AN

ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AN AIRWORTHY CONDITION

ISAAC DETERS A&P 2714038 IA

Annual Inspection / Propeller

07-12-2019 / 1200.0 Tach / Sensenich 74DM6-0-58 SN:A51085 / TT - 100.8 / SOH - 72.0

Inspection Complete per FAR 43 Appendix D- No Service Work Performed

Checked ADs through 2019-14 - None Due

I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED IAW AN

ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AN AIRWORTHY CONDITION

ISAAC DETERS A&P 2714038 IA

Annual Inspection / Propeller

09-04-2020 / 1272.4 Tach / Sensenich 74DM6-0-58 SN:A51085 / TT - 173.2 / SOH - 144.4

Inspection Complete per FAR 43 Appendix D- No Service Work Performed

Checked ADs through 2020-16 - None Due

I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED IAW AN
ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AN AIRWORTHY CONDITION

ISAAC DETERS A&P 2714038 IA

Annual Inspection / Propell 10-01-2021 / 1341.0 Tach / Inspection Complete per FAR Checked ADs through 2021-2	Sensenich 74DM6-0- R 43 Appendix D- No Se	58 SN:A51085 / TT -	- 241.8 / SOH – 213.0
I CERTIFY THAT THIS PROPELLER HAS E ANNUAL INSPECTION AND WAS DETERM	BEEN INSPECTED IAW AN	CONDITION ISAAC DET	TERS A&P 2714038 IA
ANNUAL INSPECTION AND THE	maua		Centions Numbers
	9/39 5 70/2	# 182 A C	1 4 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
10/28/2022 5 MOH=	389,32 Sen	sevich 740	m6-0-58
3N: A51085.	I certi	fy that this	propeller this been
# AU > 13 C. 7	Inspected		12/1/2011
13 13 15 17 9 Fe	100hr c		nd beterned to be
200	inan a	istwo-thy ci	Jon E. Covant
			ATP 4121621
			12
Time I Overhe			Certificate Numbers
Time Overha		EDP to FOR	
10/28/2622 389.32	Democes	10 10 POV	(1)
	Meinstalled	the orde of	ATTO A A
3 - 2 AT - 3 - 2 AT A	maintenar	ice. Tosqueo	and soutfied
	reinstalle	ed spinner	(N. 721982 1
BOOK SHOWER ET WY	Jan Laur Inc.	to you!	Son B. Conart
and by Association and	softed doubt	TAKEN LAST	AAP 4121621
	alt Telling	1-03 A 24	128
The said of the said			7
		/	
03/09/2023 Tach Time: 1776.45 T	Fotal AF Time: 3650.0	Prop TSO: 648.45	PROP MODEL 74DM6-0-58 / S/N
I certify this propeller has been inspected in airworthy at this time. AD notes checked th			FAR 43 Appendix D and was determined his propeller is approved for return to service at
this time.	2.		
Johnny Davis IA/A&P 003340383	Jane 1		
05/01/2025 Tach Time: 1844.93 PROP MODEL 74DM6-0-58 / 3		escription Of Your	SO: 716.93 PROP TT: 744.73
I certify this propeller has been inspect	ed in accordance with a	100 hour/annual inspe	ection IAW FAR 43 Appendix D and was
I certify this propeller has been inspected determined airworthy at this time. AD I	notes checked through is	100 hour/annual inspe ssue 2025-08. In regard	ection IAW FAR 43 Appendix D and was ds to work performed this propeller is
I certify this propeller has been inspected determined airworthy at this time. AD approved for return to service at this time downing Davis	notes checked through is	100 hour/annual inspe ssue 2025-08. In regard	ection IAW FAR 43 Appendix D and was ds to work performed this propeller is