Approving Civil Aviation Authority / Country: FAA/UNITED STATES	FA	AA Form 8130-3, AIRWORTH		3. Form Tracking Number. 18-0225
4. Organization Name and Address:		RAFT PROPELLER, LLC rossett, AR 71635	8NYR411D	Work Order/Contract/Invoice No. 18-0225
12		9	10. Serial Number:	11. Status / Work:
7. Description: 1 Hartzell Propelle	Part	Number: Quanti C2YR-1BFP 1	NS2102B	Overhaul
t. Remarks: verhauled this Hartzell Propelle aned, each part dimensionally inted and pre-balanced. Magni-assembled propeller with new //W Hartzell AD 2007-26-09 by wall other applicable AD's, i-weekly AD's checked thru thill work performed I/A/W Hartzell AD vork performed I/A/W Hartzell work performed I/A	inspected, blades values affluxed all steel paid bearings, seals, gavone time inspectives SB's, SL's and SI's date and time.	rts, Zyglo inspected all non-fiskets, and hardware. Static on and cold rolling of blade is thru this date and time. Rev 50, 133C Rev 41, 159	errous parts. balanced propeller. shanks.	
lade M/N F8468A-4, S/N's H9	96531 and H96532		14a. 14 CFR 43.9 Return to Service	Other regulation specified in Block 12
Certifies the items identified abov Approved design data a Non-approved design d	and are in a condition f	for safe operation.		n block 12, the work identified in Block 11 thed in accordance with Title 14, Code of
. Authorized Signature:	\times	13c. Approval/Authorization No.:	14b. Authorized Signature:	14c. Approval/Certificate
	1		Timothy R. April	8NYR411D
Name (Typed or Printed):	1	13e. Date (dd/mmm/yyyy):	14d. Name (Typed or Printed): Timothy R. Abney	14e. Date (dd/mmm/yyyy 10/Aug/2022
		00/00/00 User/Installer Re		10/Aug/2022
sential that the user/installer ensures nents in Blocks 13a and 14a do not ex	ccordance with the na	ational regulations of an airworthiness authority accepts aircraft eng	titute authority to install the aircraft engine/propo ness authority different than the airworthiness au ine(s)/propeller(s)/article(s) from the airworthine maintenance records must contain an installation	thority of the country specified in Block 1, sss authority of the country specified in Blo
ssential that the user/installer ensures ments in Blocks 13a and 14a do not ec nal regulations by the user/installer be	ccordance with the na	ational regulations of an airworthiness authority accepts aircraft eng	ness authority different than the airworthiness au ine(s)/propeller(s)/article(s) from the airworthine	thority of the country specified in Block 1, sss authority of the country specified in Blo
essential that the user/installer ensures ements in Blocks 13a and 14a do not co onal regulations by the user/installer be	Accordance with the nathat his/her airworthin institute installation of fore the aircraft may be	ational regulations of an airworthiness authority accepts aircraft eng	ness authority different than the airworthiness au ine(s)/propeller(s)/article(s) from the airworthine	thority of the country specified in Block 1, sss authority of the country specified in Blo certification issued in accordance with the
Propeller N Blade Mod Hub Serial I	Model_ No	ational regulations of an airworthiness authority accepts aircraft eng	ness authority different than the airworthiness au ine(s)/propeller(s)/article(s) from the airworthine	thority of the country specified in Block 1, sss authority of the country specified in Blo certification issued in accordance with the
Propeller N Blade Mod	Model_ No	ational regulations of an airworthiness authority accepts aircraft eng	ness authority different than the airworthiness au ine(s)/propeller(s)/article(s) from the airworthine	thority of the country specified in Block 1, sss authority of the country specified in Blo certification issued in accordance with the



W/O # 18-0225 08/10/2022 Abney Aircraft Propeller, LLC 106 Oak St Crossett, AR 71635

Office Phone: (870) 305-1059

TSMO: 0

TTSN: UNKNOWN

Overhauled this Hartzell Propeller M/N HC-C2YR-1BFP, S/N NS2102B, the complete assembly was cleaned, each part dimensionally inspected, blades were then ground, compression rolled shanks, painted and pre-balanced. Magnafluxed all steel parts, Zyglo inspected all non-ferrous parts. Re-assembled propeller with new bearings, seals, gaskets, and hardware. Static balanced propeller. See 8130.

*C/W Hartzell AD 2007-26-09 by one time inspection and cold rolling of blade shanks.

*C/W All other applicable AD's, SB's, SL's and SI's thru this date and time.

*Bi-weekly AD's checked thru this date and time.

*All work performed I/A/W Hartzell Manuals 113B Rev 50, 133C Rev 41, 159 Rev 80, and 202A Rev 61.

*Blade M/N F8468A-4, S/N's H96531 and H96532.

CRS#8NYR411D

Signature Timothy R. Abrus

08/27/2022

N8796W

Hartzell HC-C2YR-1BFP

Tach 3695.74

TSOH 0.0

Prop TTSN UNKNOWN

Removed Hartzell propeller HC-C2YK-1BF and installed overhauled Hartzell Propeller model HC-C2YR-1BFP, S/N N2102B, Overhauled by Abney Aircraft propeller, LLC. Work Order 18-0225, see FAA Form 8130-3, dated, 10/AUG/2022. Installed in accordance with Hartzell Propeller manual 115N 61-00-15 REV 24 dated Dec 2020. Negligible weight and balance change. Run up aircraft and performed operational check, no defects noted. Danny Battles A&P3498190IA Tanny Battles