lanufact	28-Z	Piper 1429	4			Model Registration	PA Z8	167	201
EAR 0 13 ATE	RECORDING TACH TIME	TODAY'S FLIGHT		1025	Dav		Aviation 03FR571X		-A6.
Im 1-				SCAL	LE CORREC	CTIONS	ALTIMETI	ER S/N: 7	5210
12-12				Altimeter	Add Alge	ebreically	Altimeter	Add Alge	
				Reads	Room°C Temp	Low °C Temp	Reads	Room C Temp	Low C
				-1,000	-20		16,000	+10	Temp
				0	-20		18,000	-10	
				500	-10		20,000	-20	
				1,000	-10		22,000	/	
				2,000	-10		25,000		70.000
				3,000 4,000	-20		30,000)	
					-25		35,000		
		Note		8,000	-10		40,000	7	
				10,000	-20		45,000		
				12,000	-40		50,000	7	

TACH	FLIGHT	SERVICE	Technician or Repair Facility. (See back pages for other specific entries)
			The state of the s
			1 March 2014, PA-28-140, s/n 28-24424 Tach. 1039.8, total time 6084.2 Annual inspection was performed IAW Piper service manual and FAR 43, apdx D. Greased and lubed A/C, grease bearings in L/G, replaced right tire and tube. Replaced upper cone p/n RD-0097-00B. All ADs complied with, AD 95-26-13 Due @ tach 1139.8. New AD 2013-02-13 c/w. "I certify that this aircraft has been inspected in accordance with annual inspection and was determined to be in airworthy condition." James Tyler A&P IA, 3171337
8.8201		6084.2	PMOVED AND REPLACED RUDDEN. PM 63540-02. CHECKED CABLE TENSION AND SOFTED TWANGUELES. TESTED ELT AND CHECKED GOOD. & ATMCKAFT Fand TO BE AIM WONTHY. JAMES TYLEN AIPIA MAN.
	TIME		TIME SERVICE

DOOMTOWN AVIATION LLC. OKLAHOMA CITY, OKLAHOMA

JAMES "ROCKE" TYLER, AÅP, IA -WILEY POST AIRPORT, KPWA HANGER 1502

7 June 2014 Piper PA-28-140, s/n 28-24424, N6720J Tach. 1121.3, TT 6165.7

100hr inspection was performed IAW Piper service manual and FAR 43, apdx D. Grease & lubed aircraft, greased & packed bearings in landing gear. Check cable tensions, adjusted aileron & rudder cable and saftied. Replaced ELT batteries p/n BP-1040, C/W FAR 91.207, ELT function test & inspection, battery change next due 6/2016. Opened all inspection panels and inspected aircraft for cracks, corrosion and damage.

"I certify that this AIRCRAFT has been inspected in accordance with 100hr inspection and was determined to be in airworthy condition."

James J. Tyler A&P IA, 3171337



the in	nplied with an Ar enspection guide. A sue ADs were con	nual/100hr. A complete Amplied with saft has been	N6720J S/N Inspection IAW AD check was of as outlined in the system. Checked inspected IAW	28-24424 TTAF: 6264.3 Hobbs: 357.9 Tach: 1219.9 We the Aircraft Maintenance manual and all routine servicing required on completed through todays date and the following reoccurring, and new the compliance requirements. AD 2013-02-13 Horizontal Stab control of the ELT operation IAW FAR 91.207. We an Annual/100 hr. Inspection and was found to be in an Airworthy condition at this time: A&P IA 2665413	ns of s.)
Se	eptember		41	Firctaff Maintenance LLC 05-306-3494 1205 5/N28-24424 Hobbs 367.2	
R R Q Q	emoved on mpone moved on TL-KT	and read v	placed eplaced were for aced he emoved	stabilator hinge bearings MICA45 I trim shaft 1-CA65246-100. It im barrel 1-CA63530-100. 12-452-413 bearings. All of the about the McFarlane beit TN BJAB-KTY Diseased forgue link kit McFarlane M cand replaced nose gear torque (sinh CA79072-000 1 each. 2 Net Aup 3370672 END	L.
YEAR 20 14 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs Entries must be endorsed with Name, Rating and Cel Technician or Repair Facility. (See back pages for oth	rtificate No.
9/16	1228.6		367.7	According to return and is ready to return to service. Part a 3202288 Coch	
complete	ed with an Annu ection guide. Re ed through today ince requirement	April 12, 201 al/100hr. In placed the ri s date and t s. AD 2013- has been in	5 N6720J spection IAW ight brake pac the following s 02-13 Horizon spected IAW a	ircraft Maintenance LLC 405-306-3494 S/N 28-24424 TTAF: 6373.7 Hobbs: 467.3 the Aircraft Maintenance manual and all routine servicing required and checked for any leaks on the caliper. A complete AD chereoccurring, and new issue ADs were complied with as outline that Stab control system. Checked the ELT operation IAW FAR an Annual/100 hr. Inspection and was found to be in an Airwoon ondition at this time. A&P IA 2665413	eck was

					R
	Reli	able Aircraft	Maintenan	ce LLC	9
			06-3494		36
Au	0		24424 TTAF:		
Complied	with a 100hr. I	nspection IAW the	Aircraft Maint	enance manual and a	all routine
servicing req	uired on the in	spection guide. Re	placed the Left	brake pads and chec	ked for any
leaks on the ca	liper. Removed	d and replaced LT	MLG Tire. Rem	noved and replaced N	NLG Tire and
tube. A comp	olete AD check	was completed th	rough todays d	ate and the following	g ADs were
complied w	ith as outlined	in the compliance	requirements.	AD 2013-02-13 Horiz	ontal Stab
	control syst	em. Checked the I	ELT operation L	AW FAR 91.207.	
I certify this a	ircraft has been	n inspected IAW a	n Annual/100 h	r. Inspection and wa	is found to be
	i	n an Airworthy co	ondition at this	time.	
		01.1			
	Erik Alan	Gross Cit 4		A&P 2756964	
			PA		
			11		
		Relia	ble)		
		Brian Butler (40)	1TENANCE 5) 306-3494		
		Brian Bullet 140	3, 300 0 17		
	N0700 I	Model:	PA28-140	Date:	12-13-2015
Registration:	N6702J 28-24424	TTAF:	6623.0	Hobbs/Tach:	716.6 / 1524.9
S/N:	20-24424				
complied with an	Annual/100hr In	spection IAW the A	ircraft Maintena	nce manual and all	routine servicing
wired on the inci	paction audo Inc	enected and llibrical	ren all ninge bol	1115, Cables, and pur	icyo. Oncomea a.
erior and exterior	lights for normal	operation, Remove	ed the left main	the and tube, mape	cled the whice a
ach bolts. Installe	ed a new 6X6.00	tire and tube, servi	ced all tires to n	ormal operating pre	SSUIES. CHECKEL
ELT operation		l cortifu that the me	aintananca daci	orinad anova nas n	
accordance with	Appual increase	n and was favored to	ho in on Aires	cribed above, has b	cerr accompliance
accordance with	Annual inspectio	n and was found to	be in an Airwor	thy condition.	cerr accompliance

YEAR	The state of the s	ORDING	TODAY'S FLIGHT	TOTAL TIME IN	E	167207	Davi	CR	S # D3	viation, BFR571X	United	1472
0	TIM		FLIGHT	SERVICE	Ī		E CORREC				R S/N: 73	
ATE					AI	SCAL				ALTIVILIE	Add Alge	
TAIL	NUM:	N6720J			4	Altimeter	Add Alge	Low	-	Altimeter	Room C	Low C
N	AKE:	PIPER			7	Reads	Temp	Ten	Charles and the same of the sa	Reads	Temp	Temp
MC	DEL:	PA-28-1	40		00 isko	-1.000	-20			16,000	-70	
				The second second second second	8) 68	0	-10			18,000	-0-	
The state of the s	S/N:	28-2442				500	-5			20,000	-60	
certify th	at th	e altim	eter, P/N	I: LA72-11	, S/I	1,000	-10			22,000	(
anconnde	r. G	TX 327	, S/N: 83	713/9/ te	ests,	2.000	-10			25,000	1	2
erformed	and	found	to com	oly with 1	4 CI	3,000	-20			30,000	-	
rrespond	lence	was c	ertified	to 20,000	feet	4,000	-55	-	_	35,000		
no in acc	orda	nce wit	th curren	t regulation	ns o	6,000 8,000	-0-			40,000)	
tails of th	o m	aintena	nce are	on file at th	nis re	10,000	+10			50,000	1	
talls of th	16 111	annecha	1.			12.000	-30	+		30,000	1	
ned: _/	1.	- 08	1,00	Geo	orge F	14.000	-10	-	-			
-	600	71 4	mun's	oa		-		21		DATE:	12-16	. 72
						BY: 6	eorgek	du	1500		1276	-201
ATE	TIME		9	ENVIOL	IECI II IIC	an or nopa						
TAILN	UM.	N6720J		A	DAVI	S FIELD		_	V	VORK ORDER:	1984	
		PIPER		A	VIA	S FIELD TIOI	N, LL	C	,			
	AKE:			1200	Sabre	St				TACH TIME:		
MO	DEL:	PA-28-140				K 74403					42/45/200	
	5/N:	28-24424			82-4101					ired by 14	12/16/203	
erformed orresponde one in acco	and i	found to was cer ce with	o comply tified to current r	with 14 (20,000 fee egulations file at this r	t. The of the legal repairs	rt 43, app maintenar FAA and is	endix E a nce involv approved er work o	and F red or I for r order I	The and this and the thick the thick the thick the thick the the thick the t	ired by § 9 altimeters aircraft ide o service the bove.	and enco	oder da bove w
21 1	JAN eb,	2016	N67	'20J		Tach 1,						
p/n CA3	CA3	35328 28-800	-800E, E-MAI	s/n 9308	as p	er STC	SA02	410	AT. C	oducts F locumer nual. No	nt Num	ber
							Dilan		,			
							DHuff David	nav	the market			
							David	Huff	man			
							A&P31					
							MOLES	UJJ	HUIA			



			DAGG 140	Date:	3-22-2016
Registration:	N6720j	Model:	PA28-140	Hobbs/Tach:	820.4 / 1611.3
A/F S/N:	28-24424	I IAF.]			

Removed the damaged brake reservoir and installed a new ACS Products Co. reservoir model A-315. Fabricated a mount plate to pick up the original mount holes and installed with a new rubber hose to the hand brake cylinder. Serviced with fluid and checked for leaks, none noted. The maintenance described above, has been accomplished in accordance with current Federal Aviation Regulations and is approved for Return to Service.

Brian Butler

A&P IA 2665413



Registration:	N6702J	Model:	PA28-140	Date:	5-12-2016
S/N:	28-24424	TTAF:	6742.1	Hobbs/Tach:	835.7 / 1624.0

Complied with an Annual/100hr. Inspection IAW the Aircraft Maintenance manual and all routine servicing required on the inspection guide. Inspected and lubricated all hinge points, cables, and pulleys. Checked all interior and exterior lights for normal operation. Checked the condition and service life of the brake pads. Serviced all tires to normal operating pressures. Checked the ELT operation IAW FAR 91.207. I certify that the maintenance described above, has been accomplished in accordance with Annual/100 hr. inspection and was found to be in an Airworthy condition.

Brian Butler _____ A&P IA 266513

		N6702J 28-24424	TTAF:	6815.0		
			Model:	PA28-140	Date: Hobbs/Tach:	1-23-2017 944.2 / 1716
		A B	Recent MAIN rian Butler (40.5	ALANIC -		
			7 10	Ha	Britton Cla	ee Pending Airfran
			good.		FARCA	2
			2/N 50	00055 P/N	Fronics Voltage R RISTOL. Ops	check
1042016	Tadh: 83.6	Holdor. 906, a	2 TT: 6801	7 N67	20J	poulator
				uffman vid Huffman P3109340IA		
	Fabricated ne and AN 426 r	ew engine cowl, ivets. Installed r	new cowl.	e p/n 63603-08. Use	ed 2024-T3 .032	
	5 Jun, 2016	N6720J	Tach 1,632.	5		

Brian Butler ___

____ A&P IA 266513

YEAR 2017	RECORDING TACH HISTORY TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
0011	D	PI	70 2001	completed Complied with 100 hr inspection in remanual, and all routine servicing required on
the ins	pection	guice	201 10	7) (DIVIZIZIZIONI)
tospec	ted and 1	Jor Ca	Ca Cart	The state of the s
aperati	ng press	ore. K	Tal DIA	DA DQ-18-1 Remarked ER-2RCD Foole ELT.
InStal	red Art	ex El	1393	and silver El Toperation IAW FAR
91.20	7. K41	w	plirect S	Day attitude emortal. I all miscellaneous
- hardy	sare Ma	in Lanc	Ing Gear	Torque Links of 2 molecement Aug2023
- Arte	ACR ELECTR * Products - C Fort Lauderd * ENTRY N 3	CAGE Code ale, FL 33:	10. e 18560 312	or tach 2423,5. Horizontal Stab Control or tach 2423,5. Horizontal Stab Control (AD 2013-02-13) due OB- 2021, Icotty that the maintenance describedabove, has been accomplished in accordance w 100hr. inspection and was found to be in an accordance w 100hr. inspection and was found to be in an accordance w 100hr. inspection and was found to be in an accordance w 100hr. inspection and was found to be in an accordance w 100hr. inspection and was found to be in an
20 DATE	TIME		OL.	- 1 Hiterla aura serial #41293F, model-
23/Nov 2017	CONTROL OF			#5000B-9 and replaced with direct exchange attitude gyro serial #88876F, model #
		(() () () () () () () () () (10 m	5000R-2D. Performed ops check and
Ho Ass			N (AS)	attitude gyro operated correctly.
	158 N 19			Britton C Lee 3202288 AP

Capital Aviation, Inc.

5500 Phillip J. Rhoades • Hanger 17 Wiley Post Airport • Bethany, OK 73008 • (405) 495-1141 • Fax (405) 495-1153

Make & Model: Piper PA-28-140

Date: 12-11-2017

LOG ENTRY

Reg. No: N6720J S/N: 28-24424

Altimeter P/N: LA-72-11

#1 XPDR 011-00490-00 83713797

S/N: 73319

on Perch

Performed 14 CFR 91.411 and 14 CFR 91.413 tests and inspections. Reference 14 CFR Part 43 Appendix E and 14 CFR Part 43 Appendix F for work performed.

All work performed complies with current Federal Aviation Regulations. This aircraft is approved for return to service with respect to the work performed. Details are on file at this facility under W/O #2947.

Signature

Brian Reich

CRS# X91R092Y



			PA28-140	Date:	2-9-2018
Devictorion:	N6702J	Model:	7005.8	Hopbs/Tach:	1178.6/1907.1
Registration:	28-24424	TTAF:	7000.0		

Complied with an Annual/100hr. Inspection IAW the Aircraft Maintenance manual and all routine servicing required on the inspection guide. Inspected and lubricated all hinge points, cables, and pulleys. Checked all interior and exterior lights for normal operation. Replaced right rudder rod tube (P/N 63327-002). Replaced air filter with bracket filter (BA3) and instrument air filter with Rapco Air filter (P/N RA-D9-18-1). Replaced fuel hose (P/N 63901-14) with owner made part. Serviced all tires to normal operating pressures. Checked the ELT operation IAW FAR 91.207. AD 2013-02-03 Horizontal Stab control (Due 8-2021). Main landing gear torque links (AD 72-08-06) due again at 2007.1. AD 95-26-13 Oil hoses (Visual Due @ 2007.1) (Replacement Due Aug 2023 or 2423.5 tach). AD 2018-02-05 has been visually inspected and verified for proper fuel tank placard installation. I certify that the maintenance described above, has been accomplished in accordance with Annual/100 hr. inspection and was found to be in an Airworthy condition.

Brian Butier

A&P IA 266513

YEAR 20 1 B	TACH TIME	FLIGHT	TIME IN SERVICE	Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
13Jun 2018	Tach: 2002.6	1795,8	7,101,3	Complied with a 100hr inspection in reference to aircraft maintenance
28-24424				ranual and all routing servicing required on the inspection guide.
20 211		Inspecte	dard lubr	catedall hinge paints, oables, and pulleys. Chechedal interior and
		exterior ?	ights forme	smal operation. Checked the condition ardservice Theofthe
	1			ad three new 6x 6,00 tires and trebes, serviced all tires to
				essens. Checked the ELToperation IAW 91, 207, B+R
		air filter	with rew	broadlett air Filter PIN BA3. Removed Turn Coordinator PIN
				H. Renstalled OH tun coordinator and verified proper
				unding Gen Torque Links CAD 72-08-06) due again tach 2102.6.
				prizental Stab, due 08-2021. AD 2017-14-04, Engine
				due tach 2102.6, replace by 08-2023 or tach 24235.
		AD 76-	07-12 I	intion Switches, next due again tach 2102.6. AD 70-16-05,
		Extrust	Maffler de	eagan tach 2102.6, I cotify that the maintenance
		describe	dabove.	has been accomplished in accordance with 10 hour
		insartia	n and fou	nd to be in an Airworthy Condition.
		Britto	n C.I.	e Falla 3202288 A+P
		011/0	10.00	(10 7 (20))

P.July 2018	Tack 2021,2	17056s 1319.2	7,119,9	va cuum p		215CC, S/N/	
	aliteri marka		L., 50	correctly		Lee FOHCa	simp operated
Registratio		N6702J	AIR Brio	CRAFT MAIN IN Butler (40.	NTENANCE 5) 306-3494		
S	/N: 2	28-24424		Model:	PA28-140 7194.7	Date: Hobbs/Tach: ual and all routine serecker cable tonsing	1-19-2019 1411.8/2096

aileron, rudder and stabilator tensions. Checked all interior and exterior lights for normal operations and readjusted with bracket filter (BA3) and instrument air filter with Rapco Air filter (P/N RA-D9-18-1). Serviced all tires to normal operating pressures. Replaced four new Cleveland brake liners (P/N R6-105) Checked the ELT operation IAW FAR 91.207. ELT Battery replacement date Aug 2024. AD 2013-02-03 Horizontal Stab control (Due 8-2021). Main landing Babve, has been accomplished in accordance with Annual/100 hr. inspection and was found to be in an Airworthy

Brian Butler A&P IA 266513

DATE	N67205 ECT Aug 2024
FEB/21/2020 Hobbs: 1454.3	Complete with An Annual / looker
[ACH 2130,3	Inspection I Aw AIRCRAFT Nantone
1 ACI 2130,3	marriel, buled all control Colos) polley
	Sever Brake Res. AP. 2017-14.04
	Viound Due of 2190.0, AP 2013-02-03
	Hozi Zoulel GAB Coutrol Ane (8-200)
	AD 72 = 08-06 Due agin At 2596.0
	A0 30 76-07-12 jarden Suth die
	Agin 2196.0. I laty that The Awest
	has been wanted Asl Accordance with
	am 100lise Anoral Toxistion And was
	bund to be a an An with Constitution
	fund to be a an Are worty Constitue
	ENGG BUTER
	AP003875255IA

YEAR 20 10 DATE	TACH TIME	FLIGHT	TIME IN SERVICE	Entries must be endorsed with Name, Hating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries)
8/22	2001 To	S. Sanda	A me	RG: 35, AKC, Torqued & Betty brex clear. Mr. M. HENNEBRY 3698623
and of		-\$50000	AND	
40				Aircraft Maintenance Record
80			Tail Num	nber: N6720J Serial Number: 28-24424 TACH HRS: 2144.1 Work Order Number: 1916 Date: 08OCT2020
2001	Page 1 of 1			STOR GLOCAL TOTAL DATE. GOOG 12020
0	S/N N14189	9. Above syste	ems and comp	s required by 14 CFR 91.411 have been accomplished with reference to CFR part 43 d Instruments Altimeter P/N: 5934PA-72 S/N: 7991. Trans-Cal Encoder P/N: SSD120-30N ponents were tested to 20.000' using Laversab model 6300, S/N 86167.
A 30				required by 14 CFR 91.413 were performed and found to comply with CFR Part 43 inder P/N 011-00490-00 S/N 83713797. Tested using Aeroflex IFR 6000, S/N 1000684925.
	AeroVets Av	viation, LLC	to service.	
		yce P. Font	enot, CRS# A	IVAR827D
			HVILE	[BOTHHOIGH ST. 1-F-
20	IME			N 6720 J ECT Aug 2024
APRIL/3/	1021 Hobbs	5:147	8.9	
				Troplaire IAW ARCRAFT Manteurl manual luled all Control Cables pullys
				Sever Broke lesson Ap 2017-14-04
				Visual Due at 290.0, AD 2013-02-03

AD, 72-08-04 Que again et 2596.0

again 2196.0. I Certify that this amount

My Britt BUTLOR

AP 00307525 IA

July 25, 2022 Piper Cherokee N6720J SN 28-24424 / Tach Time: 2167.1/ Total time: 7,282.7/ Hobbs: 1499.8

Jacked up aircraft and repacked wheel bearings. Replaced both main wheel brake disc PN 164-02000, Replaced brake linings PN 066-10500, And removed and re-seal parking brake PN 455-938 with seal kit PN 04-04043 and reinstalled. Brake system serviced 5606 and re blead. Inspected and lubricated all hinge points.

Scotty Butler

A&P 3021434

July 25, 2022 Piper Cherokee N6720J SN 28-24424 / Tach Time: 2167.1/ Total time: 7,282.7/ Hobbs: 1499.8

Checked recurring Ads thru bi-weekly this date. C/W AD 2013-02-13 next due July 2029 or TTAF 9,282.7. C/W AD 76-07-12 Next due 2196.0. ELT battery due August 2024. Checked ELT IAW FAR 91.207(d). 14 CFR 91.411 & 14CFR 91.413 check due 08/2022.

I certify that this aircraft has been inspected IAW an annual inspection and was found to be in an airwarthy condition at this time.

Greg Butler

A&P 003075250IA

July 27, 2022 Piper Cherokee N6720J SN28-24424/ Tach Time: 2167.1/

Total Time: 7,282.7/ Hobbs: 1499.8

Remove ELT unit from aircraft Artex ELT 345. Installed new Artex ELT 345 unit with new battery. Replacement battery date November 2028. Tested ELT IAW FAR 91.207(d). With work stated above, aircraft is returned to service.

Scotty Butler

A&P 3021434



AeroVets Aviation, LLC., 6600 S Mustang Field Rd Hangar 4, El Reno OK (405) 276-2011. Date: 06-06-2023 Logbook: Airframe Tail Number: N6720J

Tach: 2183.5 Model: PA-28-140 Serial: 28-24424

ATC transponder tests and inspections required by 14 CFR 91.413 were performed and found to comply with CFR Part 43 Appendix F. Garmin GTX327 Transponder P/N 011-00490-00 S/N 83713797 Tested using VIAVI AVX-10K S/N 1000000297.

The work described on the above work order was performed in accordance with current regulations of the FEDERAL AVIATION AGENCY. It is airworthy and is APPROVED FOR RETURN to service.

Repair Station: AVAR827D | Authorized RTS Technician: Jeremy Michaels

Sign: Date: 06-06 September 3, 2023 Piper Cherokee N6720J SN 28-24424 / Tach Time: 2189.6/ Total time: 7,305.2/ Hobbs: 1527.3

Jacked up aircraft and repacked wheel bearings. Replaced LH brake O-ring with new. Brake system serviced 5606 and re blead. Inspected and lubricated all hinge points. Installed grommet RH wing nav light power wire. Replaced engine primer O-rings with new. Replaced all engine hoses firewall forward with new hoses kit from precision hoses.

Scotty Butler

A&P 3021434

September 3, 2023 Piper Cherokee N6720J SN 28-24424 / Tach Time: 2189.6 / Total time: 7,305.2 / Hobbs: 1527.3

Checked recurring Ads thru bi-weekly this date. C/W Ad 2017-14-04 by replacing all hoses, next due 082028. C/W AD 2013-02-13 next due July 2029 or TTAF 9,282.7. C/W AD 76-07-12 Next due 2296.0. ELT battery due 11/2028. Checked ELT IAW FAR 91.207(d). 14CFR 91.413 check due 06/2025.

I certify that this aircraft has been inspected IAW an annual inspection and was found to be in an airworthy condition at this time.

Greg Butler

A&P 00307525 IA

10/26/24 PA28-140 N6720I SN 28-24424 Tach Time: 2,209.7

Hobbs: 1,551.8 TTAF: 7,325.3

Replaced LH fuel cap gasket w/new PN CA66615-000A. Replaced O-rings is Primer W/new PN MS 29513-012. Serviced air in tires. Tighten up hardware on head set plug in jacks. Replaced instrument air filter W/new and vacuum relief filter W/new. Replaced one brake line hose to brake handle W/new. Installed new Flight strobe FS-4400 assembly on top of vertical stabilizer. Fabricated new aluminum bracket for power plug in on bottom of the RH side instrument panel.

Scotty Butler_

A&P 3021434

10/26/24 PA28-140 N6720J SN 28-24424 Tach Time: 2,209.7

Hobbs: 1,551.8 TTAF: 7,325.3

Jacked up aircraft and repacked wheel bearings. Removed all access panels and lubed all flight control ends. Checked AD's thru bi-weekly this date. AD 76-07-12 Next due: 2296.0. Visual inspection of AD 2020-24-05. ELT battery due 11/2028. Checked IAW FAR 91.207(d). 14 CFR 91.413 next due:

I certify that this aircraft has been inspected IAW an Annual inspection and was found to be in an airworthy condition at this time.

Scotty Butler

A&P 3021434 IA