

Textron (Beech) A36

**Airworthiness Directives
Compliance Report**

Date: 8/4/2025	Tail #: N24LK	Hours: TT: 7048.0 Tach: 699.0 TSMOH: 2098.0
Airframe: Textron (Beech) A36	S/N: E-1744	Hours: 2098.0
Nose Engine: Continental IO-550-B	S/N: 834713-R	Hours: 3902.2 Hrs.
Propeller: Hartzell PHC-C3Y Series	S/N: EE4361B	

Airframe: Textron (Beech) A36						
AD# Eff Date Category	Subject	Date/Hours at Compliance	Method of Compliance	Rec	Date/Hours Next Due	Signature and Number
70-12-02 06/09/70 Airframe	Center Seat Tracks		This S/N aircraft not effected.		N/A	Mike Rowell 3038853
71-24-10 08/01/73 Airframe	Security of Control Wheel		This aircraft S/N not effected.		N/A	Mike Rowell 3038853
72-11-02 05/20/72 Airframe	Engine Fuel Interruption		This S/N aircraft not effected.		N/A	Mike Rowell 3038853
73-14-03 07/06/73 Airframe	Landing Gear Shock Strut Piston		This S/N aircraft not effected.		N/A	Mike Rowell 3038853
74-03-02 02/05/74 Airframe	Landing Gear Strut Pistons		This aircraft S/N not effected.		N/A	Mike Rowell 3038853
74-12-02 06/05/74 Airframe	Aft Facing Seats		This aircraft S/N not effected.		N/A	Mike Rowell 3038853
74-24-03 11/22/74 Airframe	Strobe Light System		This aircraft S/N not effected		N/A	Mike Rowell 3038853
75-05-02 02/21/75 Airframe	Engine Oil		N/A this aircraft has not been modified in accordance with STC SA2653WE, Beryl Aviation air oil separator assembly.	Yes* (Terminating Action)	N/A	Mike Rowell 3038853
76-22-02 06/02/77 Airframe	Lap Belt Assembly		This aircraft S/N not effected.		N/A	Mike Rowell 3038853
79-01-01 01/08/79 Airframe	Screws in the Control System		This aircraft S/N not effected.		N/A	Mike Rowell 3038853
84-09-01 05/25/84 Airframe	Window Emergency Egress		This aircraft S/N not effected.		N/A	Mike Rowell 3038853
87-18-06 R1 02/05/88 Airframe	Seat Recline Actuator Handle		This aircraft is not equipped with optional hydrolock seat recline actuators.		N/A	Mike Rowell 3038853
88-20-01 10/19/88 Airframe	Firewall Material		This aircraft S/N not effected.		N/A	Mike Rowell 3038853
88-21-02 10/31/88 Airframe	Seat Tracks	9/6/1989 2057.36 Hrs.	PCW filled three aft seat positioning holes in center seat tracks of pilot and copilot seats.		N/A	Mike Rowell 3038853
91-17-01 11/25/91 Airframe	Elevator Trim Tab Actuators		PCW IAW SB 2399		N/A	Mike Rowell 3038853
91-20-08 10/31/91 Airframe	Fresh Air Blower Housing		N/A this S/N aircraft not effected.		N/A	Mike Rowell 3038853
92-18-11 10/18/92 Airframe	Landing Gear Circuit		This aircraft S/N not effected.		N/A	Mike Rowell 3038853
93-03-02 03/12/93 Airframe	Loran Receiver System		This airplane is not equipped with a Bendix/King KLN-88 Loran receiver system.		N/A	Mike Rowell 3038853
93-24-03 01/21/94 Airframe	Rudder Forward Spar	08/04/2025 7048.0 Hrs.	C/W inspected rudder for cracks.	Yes* (Terminating Action)	500 Hrs.	Mike Rowell 3038853
95-04-03 04/07/95 Airframe	Wing Carry Through Frame Inspection	08/04/2025 7048.0 Hrs.	FWD and AFT reinforcements installed at 4402 hours. Inspected FWD and AFT spar carry through frame (web) structure for cracks in accordance with the instructions in Beech Service Bulletin No. 2360, no cracks found.	Yes	500 Hrs	Mike Rowell 3038853

97-14-15 09/02/97 Airframe	Cabin and Utility Door Handle	03/05/1999 2226.5	PCW Inspected and installed new door handle with back plate.		N/A	Mike Rowell 3038853
99-09-15 05/18/99 Airframe	Flight Control Mechanism		This aircraft S/N not effected.		N/A	Mike Rowell 3038853
2000-20-14 11/28/00 Airframe	Firewall Seal		This aircraft S/N not effected.		N/A	Mike Rowell 3038853
2000-24-04 01/05/01 Airframe	Rudder Control Cable System		This aircraft S/N not effected.		N/A	Mike Rowell 3038853
2001-08-08 06/07/01 Airframe	V-Band Exhaust Clamp		N/A This aircraft does not incorporate a turbo charger.	Yes	N/A	Mike Rowell 3038853
2001-11-03 07/20/01 Airframe	Blower Motor Circuit		This aircraft S/N not effected.		N/A	Mike Rowell 3038853
2001-23-10 12/13/01 Airframe	Flap Flex Shaft		This aircraft S/N not effected.		N/A	Mike Rowell 3038853
2003-01-01 02/27/03 Airframe	Right Hand Fuselage Panel	04/13/2001 3728.1	PCW AD 200-26-16; Inspected for missing rivets in the right fuselage and installation of three missing rivets.		N/A	Mike Rowell 3038853
2007-08-08 05/25/07 Airframe	Landing Gear Uplock Rollers		This aircraft S/N not effected.	Yes	N/A	Mike Rowell 3038853
2008-13-17 08/06/08 Airframe	Circuit Breaker Toggle Switch	08/07/2009 5354 Hrs.	PCW replaced switches.		N/A	Mike Rowell 3038853
2009-25-01 01/08/10 Airframe	Pilot & Copilot Shoulder Harnesses	12/06/1994 2508 Hrs.	PCW AD 91-18-19 Inspected shoulder harness for correct washers.		N/A	Mike Rowell 3038853
2019-23-10 11/22/19 Airframe	Right Aileron Flight Control Cable End Fittings		N/A this aircraft S/N not effected.		N/A	Mike Rowell 3038853
2023-09-09 07/17/23 Airframe	Exhaust Tailpipe V-Band Coupling		N/A this aircraft does not incorporate a turbo charger or a "V" band clamp.	Yes	N/A	Mike Rowell 3038853

Nose Engine: Continental IO-550-B

AD# Eff Date Category	Subject	Date/Hours at Compliance	Method of Compliance	Rec	Date/Hours Next Due	Signature and Number
86-13-04 R3 02/24/88 Engine	Cylinder Assemblies Pressure Test		N/A this engine does not incorporate effected cylinders.	Yes* (Terminating Action)	N/A	Mike Rowell 3038853
87-14-02 10/05/87 Engine	Starter Adapter Shaftgear		N/A this engine is not equipped with a Freon compressor.		N/A	Mike Rowell 3038853
88-03-06 04/15/88 Engine	Oil Filter		N/A this engine does not incorporate effected oil filter.		N/A	Mike Rowell 3038853
88-17-03 08/10/88 Engine	Starter Adapter Assembly		N/A this engine is not equipped with air conditioning.		N/A	Mike Rowell 3038853
91-19-03 09/29/91 Engine	Collapsed Oil Filter Elements		N/A this engine does not incorporate effected oil filter.		N/A	Mike Rowell 3038853
93-10-02 08/12/93 Engine	Missing Cylinder Valve Retainer Key		This S/N engine not effected.		N/A	Mike Rowell 3038853
93-16-15 12/14/93 Engine	Fuel Pump Drive Shaft		N/A this engine does not incorporate effected fuel pump.		N/A	Mike Rowell 3038853
98-01-08 12/23/97 Engine	Exhaust Roller Rocker Arms		N/A this engine does not incorporate roller rocker arms.		N/A	Mike Rowell 3038853
99-19-01 09/30/99 Engine	Crankshaft Cheek Cracks		This engine was not manufactured between effected dates.		N/A	Mike Rowell 3038853
2000-23-21 12/12/00 Engine	Crankshaft Connecting Rod Journal Failure		This engine was manufactured after effected date.		N/A	Mike Rowell 3038853
2004-08-10 05/05/04 Engine	ECI Reciprocation Engine Cylinder Head Cracks		This engine does not incorporate ECI cylinders.		N/A	Mike Rowell 3038853
2007-04-19 R1 05/07/07 Engine	Superior Air Parts Cylinder Assemblies		This engine does not incorporate Superior Air Parts, inc. cylinder assemblies.		N/A	Mike Rowell 3038853

2009-19-07 10/07/09 Engine	EQ3 Cylinder Head Cracks		N/A The cylinders installed on tis engine were manufactured before the effected date.	Yes	N/A	Mike Rowell 3038853
2010-11-04 06/16/10 Engine	Hydraulic Lifter Face Wear		This engine does not incorporate effected hydraulic lifters.		N/A	Mike Rowell 3038853
2012-03-06 02/24/12 Engine	AVStar Fuel Servo Diaphragm		This engine does not incorporate effected AVStart Fuel Systems, Inc. fuel servo.		N/A	Mike Rowell 3038853
2014-05-29 04/25/14 Engine	SA52000-Axxx, SA55000-A1, and SA55000-A20P - (SAP) Cast Cylinder Assemblies		N/A this engine does not incorporate SAP cylinders.	Yes	N/A	Mike Rowell 3038853
2016-16-12 09/15/16 Engine	AEC/CMI Cylinder Assemblies		This engine does not incorporate ECI cylinders.		N/A	Mike Rowell 3038853
2022-16-03 08/15/22 Engine	S-1200 Series Magneto Roller Bearings		N/A this engine doe not incorporate effected model of mags.		N/A	Mike Rowell 3038853
2023-02-12 02/17/23 Engine	Intake Valve Failures		N/A All cylinders do not incorporate intake valves.		N/A	Mike Rowell 3038853
2023-05-16 03/15/23 Engine	Crankshaft Counterweight Retaining Rings		N/A this crankshaft installed is not effected.		N/A	Mike Rowell 3038853
2023-09-09 07/17/23 Engine	Exhaust Tailpipe V-Band Coupling		N/A this engine does not incorporate a turbocharge or a "V" band clamp.	Yes	N/A	Mike Rowell 3038853
2023-17-04 10/26/23 Engine	Oil Filter Adapter Gasket		N/A this model engine does not incorporate effected oil filter adapter.		N/A	Mike Rowell 3038853

Propeller: Hartzell PHC-C3Y Series

AD# Eff Date Category	Subject	Date/Hours at Compliance	Method of Compliance	Rec	Date/Hours Next Due	Signature and Number
94-17-13 09/15/94 Propeller	Propeller Hub Grease Fitting Hole Cracks		N/A this S/N propeller is not effected.	Yes	N/A	Mike Rowell 3038853
2001-07-03 06/04/01 Propeller	BASCO Serviced Propellers		This S/N propeller is not effected.		N/A	Mike Rowell 3038853
2003-13-17 07/18/03 Propeller	T and W Serviced Propellers		This propeller has not been returned to service by T and W propellers, Inc. of Chino, CA.		N/A	Mike Rowell 3038853
2005-14-11 08/17/05 Propeller	Southern California Propeller Serviced Propellers		This propeller has not been serviced by Southern California Propeller Service of Inglewood, CA.		N/A	Mike Rowell 3038853
2006-24-07 01/03/07 Propeller	Oxford Aviation/CSE Aviation Serviced Propellers		This propeller has not been serviced by Oxford Aviation Limited.		N/A	Mike Rowell 3038853
2007-26-09 01/30/08 Propeller	Fatigue Cracks	08/24/2010 5600 Hrs.	Complied with SB 61-118F R1 at OH 08/24/2010.		N/A	Mike Rowell 3038853