

Bought plane Feb 28/1978 AIRCRAFT LOG

YEAR	MO.	DAY	RECORDING TACH. READING	TIME THIS FLIGHT	TOTAL TIME	REMARKS	SIGNATURE
1978	1	30	1636.2	0.7		Training	Ray Archer
	2	24	1637.2	1.0		"	Ray Archer
	3	5	1638.2	1.0		"	Ray Archer
	3	9	1639.4	1.2		"	Ray Archer
	3	16	1640.0	0.6		"	Ray Archer
	3	18	1640.5	0.5		"	Ray Archer
	3	25	1641.6	1.1		"	Ray Archer
	3	28	1643.6	2.0		Cross Country ^{bridgeport}	Ray Archer
	3	29	1644.4	0.8		Training	Ray Archer
	4	4	1645.5	1.1		"	Ray Archer
	4	11	1646.2	0.7		"	Ray Archer
	4	17	1646.6	0.4		"	Ray Archer

CARRY TOTAL TIME TO TOP OF NEXT PAGE

DESCRIPTION OF INSPECTIONS, REPAIRS AND ALTERATIONS

Certificated mechanics or repair facilities must endorse all inspections and repairs with name, rating & Cert. No.

YEAR	MO.	DAY	DESCRIPTION
1978	4	13	oil changed 1646.2 50 wt detergent

YEAR 78		RECORDING TACH. READING	TIME THIS FLIGHT	TOTAL TIME	REMARKS	SIGNATURE
MO.	DAY					
4	20	1647.1	0.5		Training	Ray Archer
4	22	1648.4	2.3		To Fayetteville, Ark	Ray Archer
4	23	1651.9	2.5		Back to Aero Valley	Ray Archer
5	7	1652.7	0.8		Training	Ray Archer
5	14	1653.7	1.0		"	Ray Archer
5	22	1654.8	1.1		"	Ray Archer
5	24	1661.9	7.1		To Fort Scott's back	Long Roberts
5	30	1667.4	0.5		local landings	Ray Archer
6	2	1662.8	0.4		denton + back	Ray Archer
6	7	1663.4	0.6		denton + back	Ray Archer
6	9	1664.3	0.9		denton with flight maneuvers stalls + landings	Ray Archer
6	10	1665.1	0.8		landings	Ray Archer

CARRY TOTAL TIME TO TOP OF NEXT PAGE

MO. DAY

inspections and repairs with name, rating & Cert. No.

Sept. 12 changed oil - 1721.0 hours on the

1979

83

Annual + oil change 1781.4
Total time 2400 SMOH 1351 STOH 412

Certificated mechanics or repair facilities must endorse all inspections and repairs with name, rating & Cert. No.

MO. DAY

INSTALLED NEW BATTERY 2-12-80 G.K.

CHANGED OIL + SERVICED FILTERS - 2-23-80 G.K.

ARR - WEST ARL VERY WINDY + ROUGH
STEEP TURNS, SLOW FLITE
ARR - GRANBURY + RETURN
LOCAL

DATE: 3/13/80

TACH: 1813

W.O.#: 1402

Replaced bottom O-RINGS in nose strut + serviced w/ oil + air.

Glenn C. Stewart AIP 215065911

MO. DAY

4/9/80 Removed ARC RT 513A-10 SN# 622 and ARC RTA 513A SN# 609. Installed Hughes HA1000 SN# 1149 and Comsat VHF antenna in accordance with manufacturers install instructions and in compliance with recommended practices as outlined in FAR 43 and AC 43.13-2 chapters 2+3. NO electrical records required. Optional equipment list & weight & balance data brought to date.

This install in accord to W.O.# 3910 Johnson Aviation. I have inspected this install and have found it satisfactory. Technician Michael Woods

INSPECTIONS ARE DUE EVERY 12 CALENDAR MONTHS

Certificated mechanics or repair facilities must endorse all inspections and repairs with name, rating & Cert. No.

MO. DAY

5 25 CHANGED OIL + CLEANED FILTERS TACH-18330

1 24 CHANGED OIL, CLEANED FILTERS G.K.