

PROPELLER MAINTENANCE RECORD

Position _____

PITCH RANGE _____

Propeller Model HC-C3YR-1RF/F7282

High/Feather _____

Propeller S/N DY4944B

Start Lock _____

Blade Design _____

Low _____

Blade S/N's

Reverse _____

o. 1 J 58981

o. 2 J 58985

o. 3 J 58989

o. 4 _____

o. 5 _____

o. 6 _____

Aircraft Manufacturer AEROSTAR MOONEY

Aircraft Model M20F

S/N 22-0007

Registration N6822V

Spinner Assembly Part No. 835-47P

Date	TSN	TSO	AVC Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
7-27-02	0		6611.8	INSTALLED THIS NEW HARTZELL PROPELLER & SPINNER.
				A/C: 6611.8 ENG: SMOH 884.9 HOBBS: ^{1225.4} 884.9
				<i>Robert Hensley</i>
				Robert Hensley A&P 2603828

PROPELLER LOG BOOK

Date: July 10, 2002 Make: Aerostar (Mooney), Model: M20F, TTAF: 6718.3, Engine SN: RL-4429-51A, SMOH: 991.4, Prop SN: DY4944B Reg.#: N6822V
 Inspected aircraft N6822V & Hartzell Propeller, Time: 106.5 Model: HC-C3YR-1RF/F7282, Hub S/N: DY4944B in accordance with Hartzell propeller Owner's manual. I certify this propeller has been inspected in accordance with A 100 hr inspection IAW Hartzell Owner's Manual and returned to service. The end.

Robert Hensley A&P 2603829, July 10, 2002.

PROPELLER LOG BOOK

Aug 8, 2003 Make: Aerostar (Mooney), Model: M20F, TTAF: 6851.2, Engine SN: RL-4429-51A, SMOH: 1124.3, Prop SN: DY4944B Reg.#: N6822V

Inspected aircraft N6822V & Hartzell Propeller, Time: 239.4 Model: HC-C3YR-1RF/F7282, Hub S/N: DY4944B in accordance with Hartzell propeller Owner's manual. I certify this propeller has been inspected in accordance with A 100 hour inspection IAW Hartzell Owner's Manual and returned to service. The end.

Robert Hensley A&P 2603829 Aug 8, 2003.

PROPELLER LOG BOOK

Aug 24, 2004 Make: Aerostar (Mooney), Model: M20F, TTAF: 6938.6, Engine SN: RL-4429-51A, SMOH: 1211.8, Prop SN: DY4944B Reg.#: N6822V

Inspected aircraft N6822V & Hartzell Propeller, Time: 326.8 Model: HC-C3YR-1RF/F7282, Hub S/N: DY4944B in accordance with Hartzell propeller Owner's manual. I certify this propeller has been inspected in accordance with A 100 hour inspection IAW Hartzell Owner's Manual and returned to service. The end.

Robert Hensley A&P 2603829 Aug 24, 2004.

PROPELLER LOG BOOK

Sept 01, 2005 Make: Aerostar (Mooney), Model: M20F, Reg.#: N6822V TTAF: 6938.6, Engine SN: RL-4429-51A, SMOH: 1211.7, Prop SN: DY4944B

Inspected aircraft N6822V & Hartzell Propeller, Time: 326.8 Model: HC-C3YR-1RF/F7282, Hub S/N: DY4944B in accordance with Hartzell propeller Owner's manual. I certify this propeller has been inspected in accordance with A 100 hour inspection IAW Hartzell Owner's Manual and returned to service. The end.

Robert Hensley A&P 2603829 Sept 01, 2005.

PROPELLER LOG BOOK

Nov 18, 2006 Make: Aerostar (Mooney), Model: M20F, Reg: N6822V S/N:22-0007 TTAF: 7043.5, Engine SN: RL-4429-51A, SMOH: 1316.6, Prop SN: DY4944B

Inspected aircraft N6822V & Hartzell Propeller, Time: 431.7 Model: HC-C3YR-1RF/F7282, Hub S/N: DY4944B in accordance with Hartzell propeller Owner's manual. I certify this propeller has been inspected in accordance with 100 hour inspection IAW Hartzell Owner's Manual and returned to service. The end.

Robert Hensley A&P 2603829 November 18, 2006.

PROPELLER LOG BOOK

April 1, 2008 Make: Aerostar (Mooney), Model: M20F, Reg: N6822V S/N:22-0007 TTAF: 7110.98, Engine SN: RL-4429-51A, SMOH: 1392.5, Prop SN: DY4944B

Inspected aircraft N6822V & Hartzell Propeller, Time: 507.6 Model: HC-C3YR-1RF/F7282, Hub S/N: DY4944B in accordance with Hartzell propeller Owner's manual. I certify this propeller has been inspected in accordance with 100 hour inspection IAW Hartzell Owner's Manual and returned to service. The end.


Robert Hensley A&P 2603829 April 1, 2008.

PROPELLER LOG BOOK

July 9, 2009 Aerostar (Mooney), M20F, N6822V S/N: 22-0007 TTAF: 7155.50, Engine SN: RL-4429-51A, SMOH: 1437.02, Prop SN: DY4944B Prop Time: 552.2

Inspected aircraft N6822V & Hartzell Propeller, Time: 507.6 Model: HC-C3YR-1RF/F7282, Hub S/N: DY4944B in accordance with Hartzell propeller Owner's manual. I certify this propeller has been inspected in accordance with 100 hour inspection IAW Hartzell Owner's Manual and returned to service. The end.

Robert Hensley A&P 2603829 July 9, 2009.




PROPELLER LOG BOOK

Aug 9, 2010 Aerostar (Mooney), M20F, N6822V S/N: 22-0007 TTAF: 7212.21, Engine SN: RL-4429-51A, SMOH: 1493.73, Prop SN: DY4944B Prop Time: 608.9

Inspected aircraft N6822V & Hartzell Propeller, Time: 507.6 Model: HC-C3YR-1RF/F7282, Hub S/N: DY4944B in accordance with Hartzell propeller Owner's manual. I certify this propeller has been inspected in accordance with 100 hour inspection IAW Hartzell Owner's Manual and returned to service. The end.

Robert Hensley A&P 2603829 August 9, 2010.




PROPELLER LOG BOOK

Nov 1, 2011 Aerostar (Mooney), M20F, N6822V S/N: 22-0007 TTAF: 7253.60, Engine SN: RL-4429-51A, SMOH: 1535.12, Prop SN: DY4944B Prop Time: 650.3

Inspected aircraft N6822V & Hartzell Propeller, Time: 650.3 Model: HC-C3YR-1RF/F7282, Hub S/N: DY4944B in accordance with Hartzell propeller Owner's manual. I certify this propeller has been inspected in accordance with 100 hour inspection IAW Hartzell Owner's Manual and returned to service. The end.

Robert Hensley A&P 2603829 Nov 1, 2011.




PROPELLER LOG BOOK

Apr 1, 2013 Aerostar (Mooney), M20F, N6822V S/N: 22-0007 TTAF: 7253.60, Engine SN: RL-4429-51A, SMOH: 1549.1, Prop SN: DY4944B Prop Time: 664.2

Inspected aircraft N6822V & Hartzell Propeller, Time: 666.2 Model: HC-C3YR-1RF/F7282, Hub S/N: DY4944B in accordance with Hartzell propeller Owner's manual. I certify this propeller has been inspected in accordance with 100 hour inspection IAW Hartzell Owner's Manual and returned to service. The end.


Robert Hensley A&P 2603829 April 1, 2013.



PROPELLER LOG BOOK

June 15, 2014 (Mooney, Model: M20F, N6822V S/N: 22-0007 TTAF: 7279.04, Engine SN: RL-4429-51A, SMOH: 1560.55, Prop SN: DY4944B Prop Time: 689.63)

Inspected aircraft N6822V & Hartzell Propeller, Time: 689.63 Model: HC-C3YR-IRF/F7282, Hub S/N: DY4944B in accordance with Hartzell propeller Owner's manual. I certify this propeller has been inspected in accordance with 100 hour inspection IAW Hartzell Owner's Manual and returned to service. The end


Robert Hensley A&P 2603829 June 15, 2014. 

PROPELLER LOG BOOK


Aug 10, 2015 (Mooney, Model: M20F, N6822V S/N: 22-0007 TTAF: 7289.80, Engine SN: RL-4429-51A, SMOH: 1571.31, Prop SN: DY4944B Prop Time: 700.39)

Inspected Hartzell Propeller, TTIS: 700.39 Model: HC-C3YR-IRF/F7282, Hub S/N: DY4944B in accordance with Hartzell propeller Owner's manual.

I certify this Propeller has been inspected in accordance with an 100 Hour Inspection and determined to be in an airworthy condition and approved for returned to service.

Robert Hensley A&P 2603829 August 10, 2015. 

I certify I have inspected this Propeller IAW an annual/100 HR inspection, referencing the Mooney Annual/100 Hr inspection checklist and maintenance manual and have determined it to be in an airworthy condition and is approved for returned to service.

Steve Keesey A&P 002702032 IA Valid Thru 03-31-2017, Signed: 


August 10, 2015.

PROPELLER LOG BOOK


Nov 11, 2016 (Mooney, Model: M20F, N6822V S/N: 22-0007 TTAF: 7308.84, Engine SN: RL-4429-51A, SMOH: 1590.35, Prop SN: DY4944B Prop Time: 719.43)

Inspected Hartzell Propeller, TTIS: 719.43 Model: HC-C3YR-IRF/F7282, Hub S/N: DY4944B in accordance with Hartzell propeller Owner's manual.

I certify this Propeller has been inspected in accordance with an 100 Hour Inspection and determined to be in an airworthy condition and approved for returned to service.

Robert Hensley A&P 2603829 November 11, 2016. 

I certify I have inspected this Propeller IAW an annual/100 HR inspection, referencing the Mooney Annual/100 Hr inspection checklist and maintenance manual and have determined it to be in an airworthy condition and is approved for returned to service.

Steve Keesey A&P 002702032 IA Valid Thru 03-31-2017, Signed: 


November 11, 2016.

PROPELLER LOG BOOK

Nov 10, 2017 (Mooney, Model: M20F, N6822V S/N: 22-0007 TTAF: 7314.40, Engine SN: RL-4429-51A, SMOH: 1595.91, Prop SN: DY4944B Prop Time: 724.99)

Inspected Hartzell Propeller, TTIS: 724.99 Model: HC-C3YR-IRF/F7282, Hub S/N: DY4944B in accordance with Hartzell propeller Owner's manual.


I certify this Propeller has been inspected in accordance with an 100 Hour Inspection and determined to be in an airworthy condition and approved for returned to service.

Adam Anthony Dumstorf A&P 3736432 

END

November 10, 2017.

I certify I have inspected this Propeller IAW an annual/100 HR inspection, referencing the Mooney Annual/100 Hr inspection checklist and maintenance manual and have determined it to be in an airworthy condition and is approved for returned to service.

Steve Keesey A&P 002702032 IA Valid Thru 03-31-2017, Signed: 

November 10, 2017.

PROPELLER LOG BOOK

Nov 08, 2019 (Mooney, Model: M20F, N6822V S/N: 22-0007 TTAF: 7325.74, Engine SN: RL-4429-51A, SMOH: 1607.2, Prop SN: DY4944B Prop Time: 736.39

Inspected Hartzell Propeller, TTIS: 736.39 Model: HC-C3YR-1RF/F7282, Hub S/N: DY4944B in accordance with Hartzell propeller Owner's manual.

I certify I have inspected this Propeller IAW an annual/100 HR inspection, referencing the Mooney Annual/100 Hr. inspection checklist and maintenance manual and have determined it to be in an airworthy condition at this time and is approved for returned to service. -----END-----

Adam Anthony Dumstorf A&P 3736432 IA Valid Thru 03-31-2021, Signed: Adam A. Dumstorf Nov 08, 2019.

I certify I have inspected this Propeller IAW an annual/100 HR inspection, referencing the Mooney Annual/100 Hr inspection checklist and maintenance manual and have determined it to be in an airworthy condition and is approved for returned to service. -----END-----

Steve Keesey A&P 002702032 IA Valid Thru 03-31-2021, Signed: Steve Keesey November 08, 2019.

PROPELLER LOG BOOK

March 02, 2021 (Mooney, Model: M20F, N6822V S/N: 22-0007 TTAF: 7351.24, Engine SN: RL-4429-51A, SMOH: 1633.7, Prop SN: DY4944B Prop Time: 762.89

Inspected Hartzell Propeller, TTIS: 762.89 Model: HC-C3YR-1RF/F7282, Hub S/N: DY4944B in accordance with Hartzell propeller Owner's manual.

I certify I have inspected this Propeller IAW a 100 HR inspection, referencing the Mooney 100 Hr inspection checklist and Hartzell maintenance manual and have determined it to be in an airworthy condition and is approved for returned to service. -----END-----

Robert Hensley A&P 2603829 Signed: Robert Hensley March 02, 2021.

PROPELLER LOG BOOK

June 01, 2022 (Mooney, Model: M20F, N6822V S/N: 22-0007 TTAF: 7413.84, Engine SN: RL-4429-51A, SMOH: 1696.3, Prop SN: DY4944B Prop Time: 825.49

Inspected Hartzell Propeller, TTIS: 825.49 Model: HC-C3YR-1RF/F7282, Hub S/N: DY4944B in accordance with Hartzell propeller Owner's manual.

I certify I have inspected this Propeller IAW a 100 HR inspection, referencing the Mooney 100 Hr inspection checklist and Hartzell maintenance manual and have determined it to be in an airworthy condition and is approved for returned to service. -----END-----

Robert Hensley A&P 2603829 Signed: Robert Hensley June 01, 2022.

PROPELLER LOG BOOK

Aug 4, 2023 Aerostar (Mooney), M20F, N6822V S/N: 22-0007 TTAF: 7418.29, Engine SN: RL-4429-51A, SMOH: 1708.9, Prop SN: DY4944B Prop Time: 838.09

Inspected Hartzell Propeller, TTIS: 838.09 Model: HC-C3YR-1RF/F7282, Hub S/N: DY4944B in accordance with Hartzell propeller Owner's manual.

I certify I have inspected this Propeller IAW a 100 HR inspection, referencing the Mooney 100 Hr inspection checklist and Hartzell maintenance manual and have determined it to be in an airworthy condition and is approved for returned to service. -----END-----

Robert Hensley A&P 2603829 Signed: Robert Hensley August 04, 2023.

PROPELLER LOG BOOK

October 15, 2024 Aerostar (Mooney), M20F, N6822V S/N: 22-0007 TTAF: 7445.6, Engine SN: RL-4429-51A, SMOH: 1736.5, Prop SN: DY4944B Time: 865.69

Inspected Hartzell Propeller, TTP: 865.69 Model: HC-C3YR-1RF/F7282, Hub S/N: DY4944B in accordance with Hartzell propeller Owner's manual.

I certify I have inspected this Propeller IAW a 100 HR inspection, referencing the Mooney 100 Hr inspection checklist and Hartzell maintenance manual and have determined it to be in an airworthy condition and returned to service. -----END-----

Robert Hensley A&P 2603829 Signed: Robert Hensley October 15, 2024.