

**Textron (Cessna) 172N**

**Airworthiness Directives  
Compliance Report**

<b>Date:</b> 4/9/2026	<b>Tail #:</b> N738RA	<b>Hours:</b> 4741.3 Hrs. <b>Hours:</b> TSN (TTE): 56.7 Hrs. Tach: 4741.3 Hrs. <b>Hours:</b> TSN (TTP): 61.3 Hrs. Tach: 4741.3 Hrs.
<b>Airframe:</b> Textron (Cessna) 172N	<b>S/N:</b> 172-70168	
<b>Engine:</b> Lycoming O-360-A4M	<b>S/N:</b> L-42753-36E	
<b>Propeller:</b> Sensenich 76E (M76E) Series	<b>S/N:</b> 103838K	

**Airframe: Textron (Cessna) 172N**

AD# Eff Date Category	Subject	Date/Hours at Compliance	Method of Compliance	Notes	Rec Date/Hours Next Due	Signature and Number
68-17-04 09/07/68 Airframe	Stall Warning System		N/A This S/N aircraft not effected.		N/A	Mike Rowell 3038853
69-15-03 08/20/69 Airframe	Muffler Assembly Cracks		N/A This does not incorporate a Piper muffler Assembly.		N/A	Mike Rowell 3038853
71-18-01 08/31/71 Airframe	Fuel Selector Valve Placard		N/A This S/N aircraft not effected.		N/A	Mike Rowell 3038853
71-22-02 11/09/71 Airframe	Nose Gear Fork Cracks		N/A This aircraft has the later style nose gear fork, installed during production.		N/A	Mike Rowell 3038853
73-17-01 08/16/73 Airframe	Fuel Transfer Pump Operation		N/A This aircraft does not incorporate a auxiliary fuel tank.		N/A	Mike Rowell 3038853
74-04-01 02/12/74 Airframe	Aft Fuselage Bulkhead Cracks		N/A This S/N aircraft not effected.		N/A	Mike Rowell 3038853
74-06-02 03/18/74 Airframe	AVCON Mufflers		N/A This aircraft does not incorporate effected STCs.		N/A	Mike Rowell 3038853
76-21-06 09/21/76 Airframe	Engine Oil Cooler		N/A This S/N aircraft not effected.		N/A	Mike Rowell 3038853
77-02-09 02/03/77 Airframe	Wing Flap Actuator		N/A This S/N aircraft not effected.		N/A	Mike Rowell 3038853
77-12-08 06/27/77 Airframe	External Ground Power Receptacles		N/A This S/N aircraft not effected.		N/A	Mike Rowell 3038853
78-26-09 Airframe	Superseded By 79-10-14		Superseded By AD 79-10-14.		N/A	Mike Rowell 3038853
79-08-03 05/21/79 Airframe	Electrical System		N/A This S/N aircraft not effected.		N/A	Mike Rowell 3038853
79-10-14 R1 05/30/88 Airframe	Fuel Tank Venting		N/A This S/N aircraft not effected.		N/A	Mike Rowell 3038853
80-04-08 Airframe	Superseded By 01-23-03		Superseded By AD 01-23-03.		N/A	Mike Rowell 3038853
80-06-03 04/21/80 Airframe	Wing Flap Cable Clamp	03-21-1980/266.5 Hrs.	PCW Inspected for installation of Kit SK 172-60A.		N/A	Mike Rowell 3038853
81-04-04 Airframe	Superseded By 81-16-09		Superseded by AD 81-16-09.		N/A	Mike Rowell 3038853
81-05-01 03/02/81 Airframe	Incorrect Fuel Quantity Markings		N/A This S/N aircraft not effected.		N/A	Mike Rowell 3038853
81-16-09 08/13/81 Airframe	Elevator Control System		N/A This S/N aircraft not effected.		N/A	Mike Rowell 3038853
82-07-02 04/08/82 Airframe	Engine Crankcase Breather Obstruction	05-02-1982/717.5 Hrs.	PCW Oil breather tube has been accomplished.		N/A	Mike Rowell 3038853
83-10-03 06/30/83 Airframe	Control Wheel Yoke	06-18-1983/897.1 Hrs.	PCW Inspected and found accomplished in accordance with Cessna Service Bulletin.		N/A	Mike Rowell 3038853
83-17-06 09/01/83 Airframe	Aileron Balance Weights		N/A This aircraft has not been modified per Robertson STC SA1689WE.		N/A	Mike Rowell 3038853
83-22-06 11/08/83 Airframe	Aileron Hinge Pin		N/A This S/N aircraft not effected.		N/A	Mike Rowell 3038853
86-24-07 01/07/87 Airframe	Engine Controls	11-06-1987/1532.7 Hrs.	PCW Installed correct hardware.		N/A	Mike Rowell 3038853

**Engine: Lycoming O-360-A4M**

AD# Eff Date Category	Subject	Date/Hours at Compliance	Method of Compliance	Notes	Rec	Date/Hours Next Due	Signature and Number
59-10-07 07/01/59 Engine	Cylinder Baffle Clamps		N/A This engine does not incorporate cylinder baffle clamps.			N/A	Mike Rowell 3038853
64-16-05 07/10/64 Engine	Oil Seal Failure in AC Fuel Pumps		N/A This aircraft does not incorporate a fuel pump.			N/A	Mike Rowell 3038853
66-20-04 08/27/66 Engine	Oil Filter Adapter Gasket		N/A This engine does not incorporate a AC oil filter.			N/A	Mike Rowell 3038853
73-23-01 01/13/77 Engine	Piston Pin Cracks From Grinding		N/A This S/N engine not effected.			N/A	Mike Rowell 3038853
75-08-09 08/18/77 Engine	Oil Pump Drive Shaft and Impeller		N/A This S/N engine not effected.			N/A	Mike Rowell 3038853
81-18-04 R2 Engine	Superseded By 96-09-10		Superseded by AD 96-09-10.			N/A	Mike Rowell 3038853
87-10-06 R1 09/01/89 Engine	Rocker Arm Assembly		N/A This engine does not incorporate effected rocker arm shaft.			N/A	Mike Rowell 3038853
90-04-06 R1 05/28/91 Engine	Propeller Governor External Oil Line		N/A This engine does not incorporate a propeller governor.			N/A	Mike Rowell 3038853
91-14-22 Engine	Superseded By 04-10-14		N/A Superseded by AD 04-10-14.			N/A	Mike Rowell 3038853
92-12-05 07/10/92 Engine	Piston Pin Failure		N/A This engine does not incorporate effected piston pins.			N/A	Mike Rowell 3038853
92-20-07 Engine	Superseded By 93-05-21		N/A Superseded by AD 93-05-21.			N/A	Mike Rowell 3038853
93-05-21 Engine	Superseded By 93-11-11		N/A Superseded by AD 93-11-11.			N/A	Mike Rowell 3038853
93-11-11 06/21/93 Engine	Diaphragm Fuel Pumps Overhauled (by AAI) - Remove Affected Pump and Replace		N/A This engine does not incorporate a fuel pump.			N/A	Mike Rowell 3038853
94-14-13 Engine	Superseded By 95-26-02		N/A Superseded by AD 95-26-02.			N/A	Mike Rowell 3038853