

11/04/2019 Beechcraft F33A N56425 s/n CE-1469 Tach Reads 3892.10 owner: P. Baker
 Continental IO520-BB s/n 578618 TSO: 0.0
 McCauley 3A32C406-C s/n 891795 TSO: 371.5
 Reinstalled propeller after repair. I certify that this propeller has been inspected per FAR 43.15
 (a)(1)(c)(1)(2) for an annual inspection and was determined to be in airworthy condition.
 Joseph G. Silis IA405867971

06/12/2020 Beechcraft N56425 s/n CE-1469 Tach Reads 3987.5
 McCauley 3A32C(4) series s/n 891795 TSO: 466.9
 Complied with AD 07-08-04 by (h) (3) visual inspection and verification of placard installed.
 Next due annual inspection or 4087.5 tach .
 Joseph G Silis A&P405867971

12/23/2020 Tach: 4038 PropSMO: 538
 Lawrence Airmotive LLC 603-479-2067 LWMAirmotive@outlook.com
 Lawrence Municipal Airport 492 Sutton St. N. Andover, MA 01845
 N56425 ESMO: 169

Complied with an annual inspection in accordance with FAR 43 appendix D and Beech F33A annual checklist.
 Checked all AD's through bi-weekly 2020-24.
 Cleaned, dressed leading edges and repainted propeller face.
 I certify that this propeller has been inspected in accordance with an annual inspected and was determined to be in an
 airworthy condition.
 Nickolas Flammia AP3339511IA

02/01/2022 Tach: 4150 PropSMO: 650
 Lawrence Airmotive LLC 603-479-2067 LWMAirmotive@outlook.com
 Lawrence Municipal Airport 492 Sutton St. N. Andover, MA 01845
 N56425 ESMO: 281

Complied with an annual inspection in accordance with FAR 43 appendix D and Beech F33A annual checklist.
 Checked all AD's through bi-weekly 2022-4.
 Cleaned, dressed leading edges and repainted propeller face.
 I certify that this propeller has been inspected in accordance with an annual inspected and was determined to be in an
 airworthy condition.
 Nickolas Flammia AP3339511IA


HUB & BLADE INSPECTIONS

02/20/2023
 N56245
 Hour meter time 4,251.99
 TSMO 751.99
 100 hour inspection
 Researched all airworthiness directives through Bi weekly. I certify that this propeller has been
 inspected in accordance with a 100 hour Inspection and was determined to be in airworthy
 condition at this time. Inspection data: Hawker Beech service manual 36-590001-9, McCauley
 owner operator manual and, Appendix D to title 14 CFR part 43.

Gregory W. Groves 3466323 A&P

April 2 2024 Beechcraft F33A N56425 SN CE-1469
McCauley Propeller 3A32C406-C Serial # 891795 Tach Time: 4,319.3
TTSMOH 819.3

Researched all airworthiness directives this date thru bi-weekly. I certify that this propeller has been inspected IAW 100 HR inspection and determined to be in airworthy condition at this time. Using beech service manual (36-590001-9) and 14 CFR 43 APX. D. Test run okay no leaks at this time.

Scotty Butler  A&P 3021434