

PROPELLER MAINTENANCE RECORD

AIRCRAFT SERIAL AND REGISTRATION

16200042 – N5215K

PROPELLER MODEL AND SERIAL

(McCauley 1A162/TCD6754) – AEJ47003

MAINTENANCE RECORD

DATE <i>2011</i> 19	TOTAL TIME IN SERVICE		DESCRIPTION OF THE WORK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER
	HOURS	10ths		
<i>3/10</i>	<i>4</i>	<i>7</i>	Propeller S/N AEJ47003 installed new.	<i>Miguel J. Horta</i> General Aircraft Co.
<p>PROP MODEL: 1A162/TCD6754 PROP S/N: 16200042 REG. NO: 5215K WORK ORDER: 9751</p> <p> Lincoln Park Aviation Repair Station No. LKPR101K 425 Beaverbrook Road Lincoln Park, NJ 07035 Phone: 973-633-0450</p> <p>DATE: 4/5/2012 A/C TSN: 157.6 PROP TT: 183.5 HOBBS: 183.5</p> <p>Prop Entries (3) ANNUAL/PROP - Inspected propeller in accordance with 100/annual inspection.</p> <p>The Aircraft, Airframe, Aircraft Engine, Propeller or Appliance identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is Approved for return to service. Pertinent details of the repair are on file at this repair station under work order listed below.</p> <p>DATE: 4/5/2012 SIGNED: <i>[Signature]</i> Inspector 2 Work Order: 9751 Frank R Galella Certified Repair Station No. LKPR101K Printed by EBis 3 (datamedia.com)</p>				

10ths	TOTAL TIME IN SERVICE		DESCRIPTION OF THE WORK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER
	HOURS	10ths		
			<p>PROP MODEL: 1A162/TCD6754 PROP S/N: 16200042 REG. NO: 5215K WORK ORDER: 10146</p> <p> Lincoln Park Aviation 425 Beaverbrook Road Lincoln Park, NJ 07035 Phone: 973-633-0450</p> <p>DATE: 5/16/2013 A/C TSN: 161.6 PROP TT: 161.6 TACH: 161.6</p> <p>Prop Entries (3) ANNUAL/PROP - INSPECTED PROPELLER IN ACCORDANCE WITH 100/ANNUAL INSPECTION</p> <p>The Aircraft, Airframe, Aircraft Engine, Propeller or Appliance identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is Approved for return to service. Pertinent details of the repair are on file at this repair station under work order listed below.</p> <p>DATE: 5/16/2013 SIGNED: <i>[Signature]</i> INSPECTOR #2 Work Order: 10146 Frank R Galella FRG III Printed by EBis 3 (datamedia.com)</p>	

Michiana Aircraft Service, In Prop Log Entry

4323 West Progress Drive South Bend, IN 46628 Phone 574-287-4687 Fax 574-287-7753

Cesna 162

N5215K

Tach: 258.5


TPT: 258.5

Inspections:

- Complied with 100HR/Annual Inspection.

I certify that this Aircraft has been inspected in accordance with an Annual Condition Inspection and determined to be airworthy at this time. All systems interrupted have been tested and/or leak checked as necessary.

Signature:



John C Hoffa C.R.S. Q6MR956Y

Date: 9-9-13

Work Order #9942

Michiana Aircraft Service, In Prop Log Entry

4323 West Progress Drive South Bend, IN 46628 Phone 574-287-4687 Fax 574-287-7753

Cesna 162

N5215K

Tach: 355.1


TPT: 355.1

Inspections:

- Complied with 100HR/Annual Inspection.

I certify that this Aircraft has been inspected in accordance with an Annual Condition Inspection and determined to be airworthy at this time. All systems interrupted have been tested and/or leak checked as necessary.

Signature:



John C Hoffa C.R.S. Q6MR956Y

Date: 2-18-14

Work Order #9946

DESCRIPTION OF THE WORK PERFORMED

Michiana Aircraft Service, In Prop Log Entry

4323 West Progress Drive South Bend, IN 46628 Phone 574-287-4687 Fax 574-287-7753

Cesna 162

N5215K

Tach: 455


TPT: 455

Inspections:

- Complied with 100HR/Annual Inspection.

I certify that this Aircraft has been inspected in accordance with an Annual Condition Inspection and determined to be airworthy at this time. All systems interrupted have been tested and/or leak checked as necessary.

Signature: _____



John C Hoffa C.R.S. Q6MR956Y

Date: 8-7-14

Work Order #10552

Michiana Aircraft Service, In Prop Log Entry

4323 West Progress Drive South Bend, IN 46628 Phone 574-287-4687 Fax 574-287-7753

Cesna 162

N5215K

Tach: 554.5


TPT: 554.5

Inspections:

- Complied with 100HR/Annual Condition Inspection.

I certify that this Aircraft has been inspected in accordance with an Annual Condition Inspection and determined to be airworthy at this time. All systems interrupted have been tested and/or leak checked as necessary.

Signature: _____



John C Hoffa C.R.S. Q6MR956Y

Date: 4-13-15

Work Order #11041

Michiana Aircraft Service, In Prop Log Entry

4323 West Progress Drive South Bend, IN 46628 Phone 574-287-4687 Fax 574-287-7753

Cesna 162

N5215K

Tach: 585.7


TPT: 585.7

Inspections:

- Dressed prop.

This aircraft was repaired in accordance with the manufactures maintenance manual. All systems interrupted have been tested and/ or leak checked as necessary. This aircraft is airworthy and is approved for return to service with respect to the work performed.

Signature: _____



John C Hoffa C.R.S. Q6MR956Y

Date: 6-8-15

Work Order #11173

Michiana Aircraft Service, In Prop Log Entry

4323 West Progress Drive South Bend, IN 46628 Phone 574-287-4687 Fax 574-287-7753

Cesna 162

N5215K

Tach: 653.9


TPT: 653..9

Inspections:

- Complied with 100HR/Annual Condition Inspection.

I certify that this Aircraft has been inspected in accordance with an Annual Condition Inspection and determined to be airworthy at this time. All systems interrupted have been tested and/or leak checked as necessary.

Signature: _____



John C Hoffa C.R.S. Q6MR956Y

Date: 9-25-15

Work Order #11351

Michiana Aircraft Service, In Prop Log Entry

4323 West Progress Drive South Bend, IN 46628 Phone 574-287-4687 Fax 574-287-7753

Cesna 162

N5215K


Tach: 754.6

TPT: 754.6

Inspections:

- Complied with 100HR/Annual Condition Inspection.

I certify that this Aircraft has been inspected in accordance with an Annual Condition Inspection and determined to be airworthy at this time. All systems interrupted have been tested and/or leak checked as necessary.

Signature: 

John C Hoffa C.R.S. Q6MR956Y

Date: 1-6-16

Work Order #11495

Michiana Aircraft Service, In Prop Log Entry

4323 West Progress Drive South Bend, IN 46628 Phone 574-287-4687 Fax 574-287-7753

Cesna 162

N5215K


Tach: 855.0

TPT: 855.0

Inspections:

- Complied with 100HR/Annual Condition Inspection.

I certify that this Aircraft has been inspected in accordance with an Annual Condition Inspection and determined to be airworthy at this time. All systems interrupted have been tested and/or leak checked as necessary.

Signature: 

David Harrison C.R.S. Q6MR956Y

Date: 5-11-16

Work Order #11642

WRITTEN IN ERROR ??? Ref

Michiana Aircraft Service, Inc

Prop Log Entry

4323 West Progress Drive South Bend, IN 46628 Phone 574-287-4687 Fax 574-287-7753

Cesna 162 N52030

Tach: 673.5 TPT: 855.0


Inspections:

- Complied with 100HR/Annual Inspection.

Maintenance:

- Removed composite prop and installed metal prop from N5215K.

I certify that this Aircraft has been inspected in accordance with an Annual Condition Inspection and determined to be airworthy at this time. All systems interrupted have been tested and/or leak checked as necessary.

Signature: 

John Hoffa C.R.S. Q6MR956Y

Date: 5-12-16

Work Order #11657

Michiana Aircraft Service, In

Prop Log Entry

4323 West Progress Drive South Bend, IN 46628 Phone 574-287-4687 Fax 574-287-7753


Cesna 162 N5215K

Tach: 952 TPT: 952

Inspections:

- Complied with 100HR/Annual Condition Inspection.

I certify that this Aircraft has been inspected in accordance with an Annual Condition Inspection and determined to be airworthy at this time. All systems interrupted have been tested and/or leak checked as necessary.

Signature: 

David Harrison C.R.S. Q6MR956Y

Date: 7-1-16

Work Order #11731

Michiana Aircraft Service, In Prop Log Entry

4323 West Progress Drive South Bend, IN 46628 Phone 574-287-4687 Fax 574-287-7753

Cesna 162

N5215K


Tach: 1053.3

TPT: 1053.3

Inspections:

- Complied with 100HR/Annual Condition Inspection.

I certify that this Aircraft has been inspected in accordance with an Annual Condition Inspection and determined to be airworthy at this time. All systems interrupted have been tested and/or leak checked as necessary.

Signature: 

John Hoffa C.R.S. Q6MR956Y

Date: 8-12-16

Work Order #11794

Michiana Aircraft Service, In Prop Log Entry

4323 West Progress Drive South Bend, IN 46628 Phone 574-287-4687 Fax 574-287-7753

Cesna 162

N5215K


Tach: 1150.9

TPT: 1150.9

Inspections:

- Complied with 100HR/Annual Condition Inspection.

I certify that this Aircraft has been inspected in accordance with an Annual Condition Inspection and determined to be airworthy at this time. All systems interrupted have been tested and/or leak checked as necessary.

Signature: 

John Hoffa C.R.S. Q6MR956Y

Date: 10-19-16

Work Order #11924

Michiana Aircraft Service, Inc

Prop Log Entry

4323 West Progress Drive South Bend, IN 46628 Phone 574-287-4687 Fax 574-287-7753

Cesna 162

N5215K


Tach: 1250.7

TPT: 1250.7

Inspections:

- Complied with 100HR/Annual Condition Inspection.

I certify that this Aircraft has been inspected in accordance with an Annual Condition Inspection and determined to be airworthy at this time. All systems interrupted have been tested and/or leak checked as necessary.

Signature: 

John Hoffa C.R.S. Q6MR956Y

Date: 3-15-17

Work Order #12168


TNT Airworks, LLC
11038 HWY 37
Box 4, Hanger D
Hibbing, MN 55746
(218) 263-4238

Propeller Log
N5215K
06-22-2017

Hobbs: 1658.2
Tach: 1287.3
TTAF: 1287.3
TSMOE: 1287.3
TTE: 1287.3
TSMOP: 1287.3
TTP: 1287.3

Inspected hub, spinner, bulkhead and blade assemblies.

I certify that this **PROPELLER** has been inspected in accordance with an **ANNUAL** type condition inspection and was determined to be in an airworthy condition at this date.

 Thomas D. Carlson 3026196 A & P

Thomas D. Carlson 3026196 A & P IA


TNT Airworks, LLC
11038 HWY 37
Suite 4, Hanger D
Hibbing, MN 55746
(218) 263-4238

Propeller Log
N5215K
06-22-2020

Hobbs: 1670.5
Tach: 1297.2
TTAF: 1297.2
TSMOE: 1297.2
TTE: 1297.2
TSMOP: 1297.2
TTP: 1297.2

Inspected hub, spinner, bulkhead and blade assemblies, checked blade track.

I certify that this **PROPELLER** has been inspected in accordance with an **ANNUAL** type condition inspection and was determined to be in an airworthy condition at this date.

 Thomas D. Carlson 3026196 A & P

Thomas D. Carlson 3026196 A & P IA

Kramer Aircraft Services


556 Terry Crawford Dr. Hngr D123, Nacogdoches, Texas 75964
936-564-4440

6-3-2021 **N5215K** Cessna 162 S/N: 16200042 1405.5 Eng. Hrs 1405.5 TTAF

Propeller:	McCauley 1A162/TC6754	S/N: AEJ47003	1405.5 TTIS
------------	-----------------------	---------------	-------------

1. Inspected propeller for an annual condition inspection IAW FAR Part 43 Appendix D.
2. No applicable new or recurring AD's found.

I certify that the propeller identified above has been inspected in accordance with current FAA Regulations for an annual condition inspection and has been found to be in an airworthy condition.

 A&P 2698478IA

Kramer Aircraft Services


556 Terry Crawford Dr. Hngr D123, Nacogdoches, Texas 75964
936-564-4440

8-1-2022 **N5215K** Cessna 162 S/N: 16200042 1444.7 Eng. Hrs 1444.7 TTAF

Propeller:	McCauley 1A162/TC6754	S/N: AEJ47003	1444.7 TTIS
------------	-----------------------	---------------	-------------

1. Inspected propeller for an annual condition inspection IAW FAR Part 43 Appendix D.
2. No applicable new or recurring AD's found.

I certify that the propeller identified above has been inspected in accordance with current FAA Regulations for an annual condition inspection and has been found to be in an airworthy condition.

 A&P 2698478IA 8-1-2022

CONTINUED →

Date: 11/22/2023 **Hours:** Actt: 1473.2, Propeller since new: 1473.2

Tail#: N5215K

Make: McCauley

Model: 1A162

S/N: AEJ47003

I certify this propeller has been inspected in accordance with a 100hr inspection and was determined to be in airworthy condition.

A&P 3401594 I.A. Russell Scott

