

Propeller Make MCCAULEY  
Propeller Model 2A36C23-D-EG/S84B-0  
Hub Serial No. 755629  
Blade Model \_\_\_\_\_

## **Prop Works, Inc.**


Aircraft Propeller Specialists

Date: 05/07/2007

Model No: 2A36C23-D-EG/S84B-0

Serial No: 755629

This McCauley Propeller overhauled under PW1323 in reference to McCauley Manuals SPM100-R03, BOM100-R03 and 720415. All NDT complied with, no discrepancies found at this time. Installed new Parts Kit. Oil fill previously complied with. Angles checked, track checked, painted and static balanced propeller. Propeller released to service.  
TSN: Unknown TSO: 0.00 Hrs.

  
PENG YANN  
Chief Inspector

FAA Repair Station  
# ~~T47R741Y~~



N321DB HARTZELL Mod: 2A36C23-D-EG/S84B-0 Ser: 755629  
11-05-2010 Tach 3100.9 TTIS UKN TSOH Prop 421.9

1. Propeller cleaned and inspected.
2. See AD compliance listing for AD detail. All AD's complied with to date.
3. Run-up complete, operation normal.

I certify this PROPELLER has been inspected in accordance with a 100 Hour Inspection and was determined to be in airworthy condition. J R Baumann AP 2583021 IA

*SRB*

N9420S HARTZELL Mod: 2A36C23-D-EG/S84B-0 Ser: 755629  
12-02-2011 Tach 3218.3 SPOH 539.3 Hobbs 140.9

1. Propeller cleaned and inspected.
2. See AD compliance listing for AD detail. All AD's complied with to date.
3. Run-up complete, operation normal.



Work performed by Josh Word and Randy Baumann.


I certify this PROPELLER has been inspected in accordance with a 100 Hour Inspection and was determined to be in airworthy condition. J R Baumann AP 2583021 IA


*SRB*

|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                         |                                   |                        |                     |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------|------------------------|---------------------|
| <b>Integrity Airotive, LLC</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          |                                   |                        | <b>Propeller</b>    |
| <b>Hanger 54</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        |                                   |                        | <b>Tach: 3311.8</b> |
| <b>Hefner - Easley Airport</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          |                                   |                        | <b>SPOH: 632.8</b>  |
| <b>Wagoner, OK</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      |                                   |                        | <b>Hobbs:</b>       |
| <b>(918)-640-7817</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   |                                   |                        |                     |
| <b>PO No: verbal</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    | <b>Customer name: Lanny Smith</b> | <b>Reg. No: N9420S</b> | <b>S/N: 755629</b>  |
| Cleaned blades and hub and visually inspected propeller assembly for nicks, cracks, abrasions, corrosion and found OK. Checked blade to hub fit / security and found OK. Inspected balance weights for security of attachment and found OK. Visually inspected propeller spinner and backplate for cracks and general condition and found OK. This propeller has been inspected in accordance with a 100 hour inspection and the Mcauley Maintenance Manual no. 720415 and was determined to be in an airworthy condition on this date. |                                   |                        |                     |
| <b>Date: 1/1/13</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     | <b>James P. Stiles AP3412843</b>  |                        |                     |




|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   |                                                                                                                     |                                                                         |             |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------|-------------|
| 1/1/13 Tach. <u>33118</u> Hobbs N/A ACTT <u>6549.8</u><br>Performed Annual/100 hr inspection in accordance with Mc<br>Cauley Service Manual. I certify that this propeller has been<br>inspected in accordance with an annual inspection and found to<br>be in airworthy condition.<br><br>Jerry A. Davis A&P 3460146 IA                                                                                                                                                                                                                         |                                                                                                                     |                                                                         |             |
| <b>Integrity Air motive, LLC</b><br><b>Hanger 54</b><br><b>Hefner - Casley Airport</b><br><b>Wagoner, OK</b><br><b>(918)-640-7817</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                             |                                                                                                                     | <b>Propeller</b><br>Tach: 3459.5<br>SPOH: 780.5<br>TTIS: UNKN<br>Hobbs: |             |
| PO No: verbal                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     | Customer name: Lanny Smith                                                                                          | Reg. No: N9420S                                                         | S/N: 755629 |
| Cleaned blades and hub and visually inspected propeller assembly for nicks, cracks, abrasions, corrosion and found OK. Checked blade to hub fit / security and found OK. Checked hub to crank flange mounting studs and nuts for torque and found good. Inspected balance weights for security of attachment and found OK. Visually inspected propeller spinner and backplate for cracks and general condition and found OK. Dressed blade leading edges for minor nicks and abrasion. This propeller has been inspected in accordance with an Annual Inspection and was determined to be in an airworthy condition on this date. |                                                                                                                     |                                                                         |             |
| Date: 2/9/14                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      | <br>James P. Stiles A&P 3412843 IA |                                                                         |             |

|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   |                                                                                                                       |                                                          |             |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------|-------------|
| <b>Integrity Air motive, LLC</b><br><b>Hanger 54</b><br><b>Hefner - Casley Airport</b><br><b>Wagoner, OK</b><br><b>(918)-640-7817</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                             |                                                                                                                       | <b>Propeller</b><br>Tach: 3495.5<br>TTIS: UNKN<br>Hobbs: |             |
| PO No: verbal                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     | Customer name: Lanny Smith                                                                                            | Reg. No: N9420S                                          | S/N: 755629 |
| Visually inspected propeller spinner and backplate for cracks and general condition and found OK. Cleaned blades and hub and visually inspected propeller assembly for nicks, cracks, abrasions, corrosion and found OK. Checked blade to hub fit / security and found OK. Checked hub to crank flange mounting studs and nuts for torque and found good. Inspected balance weights for security of attachment and found OK. Dressed blade leading edges for minor nicks and abrasion. This propeller has been inspected in accordance with an Annual Inspection and was determined to be in an airworthy condition on this date. |                                                                                                                       |                                                          |             |
| Date: 3/14/15                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     | <br>James P. Stiles A&P 3412843 IA |                                                          |             |


|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            |                                                                                                                       |                                                                                 |             |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------|-------------|
| <b>Integrity Air motive, LLC</b><br><b>Hanger 54</b><br><b>Hefner - Casley Airport</b><br><b>Wagoner, OK</b><br><b>(918)-640-7817</b>                                                                                                                                                                                                                                                                                                                                                                      |                                                                                                                       | <b>Propeller</b><br>Tach: 3572.3<br>SPOH: 893.3<br>TTIS: UNKN<br>Model: 2A36C23 |             |
| PO No: verbal                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              | Customer name: Lanny Smithy                                                                                           | Reg. No: N9420S                                                                 | S/N: 755629 |
| Removed spinner. Cleaned blades and hub and visually inspected propeller assembly for nicks, cracks, abrasions, corrosion and found OK. Checked blade to hub fit / security and found OK. Inspected balance weights for security of attachment to balance ring and found OK. Visually inspected propeller spinner and backplate for cracks and general condition and found OK. This propeller has been inspected IAW an Annual Inspection and was determined to be in an airworthy condition on this date. |                                                                                                                       |                                                                                 |             |
| Date: 4/30/16                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              | <br>James P. Stiles A&P 3412843 IA |                                                                                 |             |



| Date                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                             | Total Time                                                                                                                     | Since Overhaul  | Certificate Numbers                                                                                         |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------|-----------------|-------------------------------------------------------------------------------------------------------------|
| <b>Integrity Airotive, LLC</b><br><b>Hanger 54</b><br><b>Hefner - Easley Airport</b><br><b>Wagoner, OK</b><br><b>(918)-640-7817</b>                                                                                                                                                                                                                                                                                                                                                                              |                                                                                                                                |                 | <b>Propeller</b><br><b>Tach: 3632.5</b><br><b>SPOH: 953.5</b><br><b>TTIS: UNKN</b><br><b>Model: 2A36C23</b> |
| PO No: verbal                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    | Customer name: Lanny Smithy                                                                                                    | Reg. No: N9420S | S/N: 755629                                                                                                 |
| Removed spinner. Cleaned blades and hub and visually inspected propeller assembly for nicks, cracks, abrasions, corrosion and found OK.<br>Checked blade to hub fit / security and found OK. Inspected balance weights for security of attachment to balance ring and found OK.<br>Visually inspected propeller spinner and backplate for cracks and general condition and found OK. This propeller has been inspected IAW an Annual Inspection and was determined to be in an airworthy condition on this date. |                                                                                                                                |                 |                                                                                                             |
| Date: 7/28/17                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    | <br><b>James P. Stiles A&amp;P 3412843 IA</b> |                 |                                                                                                             |

| 07-07-2021 |            | N9420S               | Model  | S/N:          | Tach  | Hobbs  | TT                 | TSOH |
|------------|------------|----------------------|--------|---------------|-------|--------|--------------------|------|
| Aircraft   | Beechcraft | V35 Bonanza          | 8015   | 3643.4 (30.9) | 613.2 | 6881.4 | 10.9 since 07-2017 |      |
| Propeller  | Hartzell   | 2A36C23-D-EG/S844B-0 | 755629 | 3643.4        |       | UNKN   | 964.4              |      |


1. Propeller cleaned and inspected.  
 2. Researched AD's. All AD's complied with to date.  
 3. Run-up complete, operation normal, no leaks.

Signature:  **J R Baumann AP 2583021**

| 05-01-2025 |            | N9420S               | Model    | S/N:   | TTAF / Air Total | SMOH / TACH | TT     | SPOH TACH -70 |
|------------|------------|----------------------|----------|--------|------------------|-------------|--------|---------------|
| Aircraft   | Beechcraft | V35 Bonanza          | 8015     | 6938.4 | NA               | 6938.4      |        |               |
| Engine     | TCM        | IO-520-BA2           | 241725-R | 6938.4 | 1091.8           | 4173.3      |        |               |
| Propeller  | McCauley   | 2A36C23-D-EG/S844B-0 | 755629   | 6938.4 |                  | UKN         | 1021.4 |               |

1. Inspect and service propeller in accordance with and Annual inspection.  
 2. Researched AD's. All AD's complied with to date.  
 3. Run-up complete, operation normal, no leaks.

This PROPELLER has been inspected IAW an ANNUAL inspection and found to be in airworthy condition.

Signature:  **J R Baumann AP 2583021 IA**



Alpha Aviation Mission Outreach Center Inc.  
P.O. Box 1622 / Davis Field Airport. Muskogee, OK 74402  
(479)856-5000

|            |            |                      |        |               |       |        |                    |
|------------|------------|----------------------|--------|---------------|-------|--------|--------------------|
| 07-07-2021 | N9420S     | Model                | S/N:   | Tach          | Hobbs | TT     | TSOH               |
| Aircraft   | Beechcraft | V35 Bonanza          | 8015   | 3643.4 (30.9) | 613.2 | 6881.4 | 10.9 since 07-2017 |
| Propeller  | Hartzell   | 2A36C23-D-EG/S844B-0 | 755629 | 3643.4        |       | UNKN   | 964.4              |

1. Propeller cleaned and inspected.
2. Researched AD's. All AD's complied with to date.
3. Run-up complete, operation normal, no leaks.

Signature: JRB

J R Baumann AP 2583021



Alpha Aviation Mission Outreach Center Inc.  
P.O. Box 1622 / Davis Field Airport. Muskogee, OK 74402  
(479)856-5000

|            |            |                      |        |        |       |        |       |
|------------|------------|----------------------|--------|--------|-------|--------|-------|
| 06-04-2024 | N9420S     | Model                | S/N:   | Tach   | Hobbs | TT     | TSOH  |
| Aircraft   | Beechcraft | V35 Bonanza          | 8015   | 3652.1 | 623.2 | 6890.0 |       |
| Propeller  | McCauley   | 2A36C23-D-EG/S844B-0 | 755629 | 3652.1 | 623.2 | UKN    | 973.1 |

1. Inspect and service propeller in accordance with and Annual inspection.
2. Researched AD's. All AD's complied with to date.
3. Run-up complete, operation normal, no leaks.

Signature: JRB

J R Baumann AP 2583021




**Aero Valley LLC**

Date: 03/18/2025

Reg: N9420S Tach: 3693.7

Removed Prop and Sent to Byam Propeller Services for IRAN inspection. P/N: 2A36C23-D-EG S/N: 755629. Once recieved from shop reinstalled with new nuts. Torqued Prop nuts. All work Done IAW McCauley and Beech Service Manuals. I Certify that this aircraft is in airworthy condition and will return to service at this time and date. Chris Salazar A&P003741839IA




**Alpha Aviation Mission Outreach Center Inc.**  
P.O. Box 1622 / Davis Field Airport, Muskogee, OK 74402  
(479)856-5000

| 05-01-2025 | N9420S     | Model                | S/N:     | TTAF / Air Total | SMOH / TACH | TT     | SPOH TACH -70 |
|------------|------------|----------------------|----------|------------------|-------------|--------|---------------|
| Aircraft   | Beechcraft | V35 Bonanza          | 8015     | 6938.4           | NA          | 6938.4 |               |
| Engine     | TCM        | IO-520-BA2           | 241725-R | 6938.4           | 1091.8      | 4173.3 |               |
| Propeller  | McCauley   | 2A36C23-D-EG/S844B-0 | 755629   | 6938.4           |             | UKN    | 1021.4        |

1. Inspect and service propeller in accordance with and Annual inspection.
2. Researched AD's. All AD's complied with to date.
3. Run-up complete, operation normal, no leaks.

This PROPELLER has been inspected IAW an ANNUAL inspection and found to be in airworthy condition.

Signature: 


**J R Baumann AP 2583021 IA**



**Alpha Aviation Mission Outreach Center Inc.**  
P.O. Box 1622 / Davis Field Airport. Muskogee, OK 74402  
(479)856-5000

|            |            |                      |          |        |       |        |        |
|------------|------------|----------------------|----------|--------|-------|--------|--------|
| 06-04-2024 | N9420S     | Model                | S/N:     | Tach   | Hobbs | TT     | TSOH   |
| Aircraft   | Beechcraft | V35 Bonanza          | 8015     | 3652.1 | 623.4 | 6890.1 |        |
| Engine     | TCM        | IO-520-BA2           | 241725-R | 3652.1 | 623.4 | 4124.0 | 1043.5 |
| Propeller  | McCauley   | 2A36C23-D-EG/S844B-0 | 755629   | 3652.1 | 623.4 | UNKN   | 973.1  |

1. Inspect and service AIRCRAFT in accordance with an ANNUAL Inspection per FAR 43 Appendix D.
2. Run-up and ops check to warm for oil change and compression check.
3. Inspect aircraft in accordance with FAR 43 Appendix D, using Beech inspection checklist.
4. Replace Brackett induction air filter BA-7112 with new Donaldson Filter PN P10-5304. Replacement due every 500 hrs. Next replacement due by 7390.1 hrs TTAF.
5. Complied with the following AD's:
6. AD 07-08-08 uplock rollers by visual inspection and lubrication, next inspection due at 6981.4 TT. (3743.4 Tach).
7. AD 94-20-04 R2 Ruddervator by visual inspection per (3)(i)(ii), next inspection due at 6981.4 TT. (3743.4 Tach).
8. AD 76-07-12 R1, Bendix ignition switch, by operational test, next inspection due at 6981.4 TT. (3743.4 Tach).
9. AD 2019-23-10 Aileron turnbuckle, by inspection per AD. No cracks, pitting or corrosion found. Found assembled per instructions. No further action required.
10. Replace Mixture control cable assembly with new MC35-944054-7, lot 80235.
11. Replace 7 FWF hoses
12. 111F417-4S0160 130524-4-0160 FUEL PRESSURE
13. 111F417-4S0130 130524-4-0130 FUEL PRESSURE
14. 111F417-4S0170 130524-4-0170 VAPOR RETURN
15. 111F417-6S0185 130524-6-0185 FUEL SUPPLY
16. 124F001-4CR0380 635158S4S-38.00 TEF W/F/P TO CONTROLLER
17. 124F001-4CR0380 635158S4S-38.00 TEF W/F/P TO CONTROLLER
18. 124F001-4CR0320 635158S4S-32 TEF W/CONTROLLER TO M/V
19. Engine Run-Up and Operational check of systems and radios are OK.
20. Interior removed for re-upholstery.

Signature: 

J R Baumann AP 2583021


5-17-2024 Radio Installation by Davis Field Aviation.



**Alpha Aviation Mission Outreach Center Inc.**  
P.O. Box 1622 / Davis Field Airport. Muskogee, OK 74402  
(479)856-5000

|            |            |                      |          |        |       |        |        |
|------------|------------|----------------------|----------|--------|-------|--------|--------|
| 06-24-2024 | N9420S     | Model                | S/N:     | Tach   | Hobbs | TT     | TSOH   |
| Aircraft   | Beechcraft | V35 Bonanza          | 8015     | 3652.1 | 623.4 | 6890.1 |        |
| Engine     | TCM        | IO-520-BA2           | 241725-R | 3652.1 | 623.4 | 4124.0 | 1043.5 |
| Propeller  | McCauley   | 2A36C23-D-EG/S844B-0 | 755629   | 3652.1 | 623.4 | UNKN   | 973.1  |

1. Interior reinstalled with new SCS carpet after radio installation.
2. Aircraft weighed with electronic scales for new weight and balance information.
3. See Equipment Change - Weight & Balance form dated 06-24-2024

Signature: 

J R Baumann AP 2583021






Alpha Aviation Mission Outreach Center Inc.  
P.O. Box 1622 / Davis Field Airport, Muskogee, OK 74402  
(479)856-5000

| 07-21-2024 | N9420S     | Model                | S/N:     | Tach   | Hobbs | TT     | TSOH   |
|------------|------------|----------------------|----------|--------|-------|--------|--------|
| Aircraft   | Beechcraft | V35 Bonanza          | 8015     | 3653.3 | 624.9 | 6891.4 |        |
| Engine     | TCM        | IO-520-BA2           | 241725-R | 3653.3 | 624.9 | 4125.3 | 1044.8 |
| Propeller  | McCauley   | 2A36C23-D-EG/S844B-0 | 755629   | 3653.3 | 624.9 | UNKN   | 974.4  |

1. STC SA3598NM Install Cockpit Sunvisor assemblies in accordance with Rosen Sunvisor Systems, LLC Master Drawing List dated 9-5-23, Revision V. FAA Form 337 this date.
2. STC SA1120SE Installed cabin Door Steward in accordance with AML SA01120SE. FAA Form 337 this date.

Signature: 


J R Baumann AP 2583021



Alpha Aviation Mission Outreach Center Inc.  
P.O. Box 1622 / Davis Field Airport, Muskogee, OK 74402  
(479)856-5000

| 10-09-2024 | N9420S     | Model                | S/N:     | Tach +3238.1=TT | Hobbs | TT     | TSOH   |
|------------|------------|----------------------|----------|-----------------|-------|--------|--------|
| Aircraft   | Beechcraft | V35 Bonanza          | 8015     | 3680.2 (26.9)   | 648.0 | 6891.4 | NA     |
| Engine     | TCM        | IO-520-BA2           | 241725-R | 3680.2          | 648.0 | 4152.2 | 1071.7 |
| Propeller  | McCauley   | 2A36C23-D-EG/S844B-0 | 755629   | 3680.2          | 648.0 | UNKN   | 1001.3 |

1. Replace light bulbs with new Aero-Lites LED's. Upper Taxi light with AL-3615X-F-PA. Lower landing light AL-46LR-2. Left NAV light AL-NM1030-G. Right NAV light AL-AL-NM1030-R. Work performed by Jason Baumann IAW appropriate service instructions.

Signature: 

J R Baumann AP 2583021



Alpha Aviation Mission Outreach Center Inc.  
P.O. Box 1622 / Davis Field Airport, Muskogee, OK 74402  
(479)856-5000

| 04-11-2025 | N9420S     | Model                | S/N:     | Tach +3238.1=TT | Hobbs | TT     | TSOH   |
|------------|------------|----------------------|----------|-----------------|-------|--------|--------|
| Aircraft   | Beechcraft | V35 Bonanza          | 8015     | 3699.3 (19.1)   | 671.4 | 6937.4 | NA     |
| Engine     | TCM        | IO-520-BA2           | 241725-R | 3699.3          | 671.4 | 4173.3 | 1090.8 |
| Propeller  | McCauley   | 2A36C23-D-EG/S844B-0 | 755629   | 3699.3          | 671.4 | UNKN   | 1020.4 |

1. Replace Aircraft Battery with new RG-35AXC. SN 70049877.
2. Replace battery ground cable with new copper cable.

Signature: 

J R Baumann AP 2583021


Completed DYNON installation.



Alpha Aviation Mission Outreach Center Inc.  
P.O. Box 1622 / Davis Field Airport, Muskogee, OK 74402  
(479)856-5000

| 04-19-2025 | N9420S     | Model                | S/N:     | Tach +3238.1=TT | Hobbs | TT     | TSOH   |
|------------|------------|----------------------|----------|-----------------|-------|--------|--------|
| Aircraft   | Beechcraft | V35 Bonanza          | 8015     | 3699.3 (19.1)   | 672.4 | 6938.4 | NA     |
| Engine     | TCM        | IO-520-BA2           | 241725-R | 3699.3          | 672.4 | 4173.3 | 1091.8 |
| Propeller  | McCauley   | 2A36C23-D-EG/S844B-0 | 755629   | 3699.3          | 672.4 | UNKN   | 1021.4 |

1. Correct times to adapt to Dynon.
2. Tach represents SMOH. 1091.8
3. Air Total represents TTAF. 6938.4
4. Begin ANNUAL

Signature: 

J R Baumann AP 2583021






Alpha Aviation Mission Outreach Center Inc.  
P.O. Box 1622 / Davis Field Airport, Muskogee, OK 74402  
(479)856-5000

|            |            |                      |          |                     |               |        |  |
|------------|------------|----------------------|----------|---------------------|---------------|--------|--|
| 05-01-2025 | N9420S     | Model                | S/N:     | TTAF<br>/ Air Total | SMOH<br>/TACH | TT     |  |
| Aircraft   | Beechcraft | V35 Bonanza          | 8015     | 6938.4              | NA            | 6938.4 |  |
| Engine     | TCM        | IO-520-BA2           | 241725-R | 6938.4              | 1091.8        | 4173.3 |  |
| Propeller  | McCauley   | 2A36C23-D-EG/S844B-0 | 755629   | 6938.4              | 1021.4        | UKN    |  |

1. Inspect and service AIRCRAFT in accordance with an ANNUAL Inspection per FAR 43 Appendix D.
2. Run-up and ops check to warm for oil change and compression check.
3. Installed Earth-X charging adapter cable with charge adapter connector at left front cowl inlet.
4. ELT inspected IAW FAR 91.207(d)/
5. Inspect Donaldson Filter PN P10-5304. Next 500 hrs replacement due by 7390.1 hrs TTAF.
6. Left wing tip strobe intermittent. Clean connector and treat with Stabillant 22.
7. Complied with the following AD's:
8. AD 07-08-08 uplock rollers by visual inspection and lubrication, next inspection due at 7038.4 TTAF.
9. AD 94-20-04 R2 Ruddervator by visual inspection per (3)(i)(ii), next inspection due at 7038.4 TTAF.
10. AD 76-07-12 R1, Bendix ignition switch, by operational test, next inspection due at 7038.4 TTAF.
11. IFR certification completed MAR 2025. Next IFR cert due MAR 2027.
12. Run-Up and Operational check of systems and radios are OK.

Work performed by Jason Baumann IAW appropriate service instructions.

This AIRCRAFT has been inspected IAW an ANNUAL inspection and found to be in airworthy condition.

Signature: 

J R Baumann AP 2583021 IA




Alpha Aviation Mission Outreach Center Inc.  
P.O. Box 1622 / Davis Field Airport, Muskogee, OK 74402  
(479)856-5000

|            |            |                      |          |                     |               |        |      |
|------------|------------|----------------------|----------|---------------------|---------------|--------|------|
| 02-20-2026 | N9420S     | Model                | S/N:     | TTAF<br>/ Air Total | SMOH<br>/TACH | TT     |      |
| Aircraft   | Beechcraft | V35 Bonanza          | 8015     | 6973.2              | NA            | 6973.2 | 34.8 |
| Engine     | TCM        | IO-520-BA2           | 241725-R | 6973.2              | 1131.3        | 4208.1 |      |
| Propeller  | McCauley   | 2A36C23-D-EG/S844B-0 | 755629   | 6973.2              | 1056.2        | UKN    |      |

1. Replace all four fuel senders after fuel sender overhaul by Air Parts of Lock Haven.
2. Re-Calibrate DYNON fuel system setup per Dynon installation and setup instructions. Emptied fuel tanks and refilled each tank 5 gals at a time and reset fuel system calibration every 5 gallons.
3. Run-Up and Operational check of systems and radios are OK.

Work performed by Jason Baumann and Randy Baumann IAW appropriate service instructions.

Signature: 

J R Baumann AP 2583021